

Model	측정 호기	시 간	내 경	판 정	진원도	판 정	원통도
T1XX-FRT	mm	8:30:04	-0.004	OK	-0.003	OK	0.01
T1XX-FRT	mm	8:30:11	-0.008	OK	0.005	OK	0.012
T1XX-FRT	mm	8:30:17	-0.006	OK	-0.003	OK	0.008
T1XX-FRT	mm	8:30:30	-0.01	OK	-0.004	OK	0.004
T1XX-FRT	mm	8:30:37	-0.01	OK	-0.001	OK	0.005
T1XX-FRT	mm	8:30:43	-0.001	OK	-0.003	OK	0.013
T1XX-FRT	mm	8:30:50	-0.006	OK	-0.001	OK	0.01
T1XX-FRT	mm	8:31:07	-0.006	OK	-0.003	OK	0.007
T1XX-FRT	mm	8:31:13	0.003	OK	-0.004	OK	0.015
T1XX-FRT	mm	8:31:33	-0.006	OK	0	OK	0.009
T1XX-FRT	mm	8:31:44	-0.004	OK	-0.004	OK	0.009
T1XX-FRT	mm	8:32:09	-0.013	NG	-0.004	OK	0
T1XX-FRT	mm	8:32:20	-0.005	OK	-0.002	OK	0.009
T1XX-FRT	mm	8:32:32	-0.006	OK	-0.003	OK	0.009
T1XX-FRT	mm	8:33:39	-0.006	OK	-0.003	OK	0.009
T1XX-FRT	mm	8:33:45	-0.006	OK	-0.004	OK	0.007
T1XX-FRT	mm	8:33:51	-0.009	OK	-0.004	OK	0.005
T1XX-FRT	mm	8:34:03	-0.008	OK	0.002	OK	0.008
T1XX-FRT	mm	8:34:15	-0.007	OK	0.004	OK	0.009
T1XX-FRT	mm	8:34:48	-0.007	OK	0.004	OK	0.009
T1XX-FRT	mm	8:34:55	-0.011	NG	0.002	OK	0.005
T1XX-FRT	mm	8:35:02	-0.007	OK	-0.003	OK	0.007
T1XX-FRT	mm	8:35:54	-0.01	OK	0.002	OK	0.006
T1XX-FRT	mm	8:36:01	-0.014	NG	0.003	OK	0.002
T1XX-FRT	mm	8:37:53	-0.014	NG	0.003	OK	0.002
T1XX-FRT	mm	8:38:06	-0.007	OK	-0.003	OK	0.006
T1XX-FRT	mm	8:38:28	-0.009	OK	-0.005	OK	0.006
T1XX-FRT	mm	8:38:40	-0.008	OK	0.001	OK	0.009
T1XX-FRT	mm	8:38:51	-0.01	OK	-0.003	OK	0.005
T1XX-FRT	mm	8:39:02	-0.01	OK	-0.002	OK	0.004
T1XX-FRT	mm	8:39:14	-0.009	OK	-0.003	OK	0.006
T1XX-FRT	mm	8:39:25	-0.008	OK	-0.005	OK	0.005
T1XX-FRT	mm	8:39:36	-0.007	OK	-0.003	OK	0.007
T1XX-FRT	mm	8:39:48	-0.009	OK	-0.003	OK	0.005
T1XX-FRT	mm	8:39:59	-0.002	OK	-0.007	OK	0.01
T1XX-FRT	mm	8:40:11	-0.004	OK	-0.003	OK	0.01
T1XX-FRT	mm	8:41:15	-0.004	OK	-0.003	OK	0.01
T1XX-FRT	mm	8:41:21	-0.007	OK	-0.003	OK	0.009
T1XX-FRT	mm	8:41:28	-0.003	OK	-0.002	OK	0.011
T1XX-FRT	mm	8:41:54	-0.003	OK	-0.002	OK	0.011
T1XX-FRT	mm	8:42:07	0.001	OK	-0.004	OK	0.015
T1XX-FRT	mm	8:42:48	0.001	OK	-0.004	OK	0.015

T1XX-FRT	mm	8:43:01	0 OK	-0.003 OK	0.015
T1XX-FRT	mm	8:43:14	-0.008 OK	-0.004 OK	0.005
T1XX-FRT	mm	8:43:21	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	8:43:27	0.004 OK	-0.006 OK	0.016
T1XX-FRT	mm	8:43:34	-0.005 OK	-0.004 OK	0.009
T1XX-FRT	mm	8:43:40	-0.002 OK	-0.004 OK	0.013
T1XX-FRT	mm	8:43:52	-0.003 OK	-0.003 OK	0.009
T1XX-FRT	mm	8:43:59	-0.006 OK	0 OK	0.009
T1XX-FRT	mm	8:44:10	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	8:44:21	-0.007 OK	-0.003 OK	0.008
T1XX-FRT	mm	8:44:33	-0.003 OK	-0.004 OK	0.011
T1XX-FRT	mm	8:44:44	-0.006 OK	-0.004 OK	0.008
T1XX-FRT	mm	8:44:51	-0.005 OK	-0.003 OK	0.011
T1XX-FRT	mm	8:45:02	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	8:45:13	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	8:47:03	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	8:47:10	-0.007 OK	0.001 OK	0.01
T1XX-FRT	mm	8:47:16	-0.003 OK	-0.003 OK	0.013
T1XX-FRT	mm	8:48:28	-0.007 OK	-0.003 OK	0.009
T1XX-FRT	mm	8:48:35	-0.006 OK	-0.002 OK	0.01
T1XX-FRT	mm	8:48:48	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	8:48:55	-0.007 OK	-0.003 OK	0.006
T1XX-FRT	mm	8:49:01	-0.007 OK	-0.003 OK	0.008
T1XX-FRT	mm	8:49:08	-0.007 OK	-0.003 OK	0.008
T1XX-FRT	mm	8:49:15	-0.007 OK	-0.003 OK	0.008
T1XX-FRT	mm	8:49:21	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	8:50:14	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	8:50:21	-0.008 OK	-0.004 OK	0.007
T1XX-FRT	mm	8:50:27	-0.004 OK	-0.002 OK	0.011
T1XX-FRT	mm	8:50:40	-0.005 OK	-0.004 OK	0.009
T1XX-FRT	mm	8:50:47	-0.006 OK	-0.001 OK	0.009
T1XX-FRT	mm	8:50:53	-0.006 OK	-0.003 OK	0.008
T1XX-FRT	mm	8:51:00	-0.01 OK	-0.003 OK	0.005
T1XX-FRT	mm	8:51:06	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	8:51:13	-0.007 OK	-0.002 OK	0.008
T1XX-FRT	mm	8:51:20	-0.006 OK	-0.004 OK	0.008
T1XX-FRT	mm	8:51:38	-0.004 OK	-0.002 OK	0.011
T1XX-FRT	mm	8:51:44	-0.008 OK	-0.003 OK	0.006
T1XX-FRT	mm	8:52:06	-0.004 OK	0.005 OK	0.012
T1XX-FRT	mm	8:52:13	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	8:52:35	-0.009 OK	-0.003 OK	0.005
T1XX-FRT	mm	8:53:25	-0.009 OK	-0.003 OK	0.005
T1XX-FRT	mm	8:53:31	-0.009 OK	-0.003 OK	0.004

T1XX-FRT	mm	8:53:38	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	8:53:57	-0.003 OK	-0.006 OK	0.01
T1XX-FRT	mm	8:54:03	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	8:54:10	-0.007 OK	-0.004 OK	0.006
T1XX-FRT	mm	8:54:21	-0.006 OK	-0.003 OK	0.008
T1XX-FRT	mm	8:54:34	-0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	8:54:45	-0.006 OK	-0.005 OK	0.008
T1XX-FRT	mm	8:54:58	-0.009 OK	-0.004 OK	0.006
T1XX-FRT	mm	8:55:29	-0.009 OK	-0.004 OK	0.006
T1XX-FRT	mm	8:55:35	-0.004 OK	-0.003 OK	0.01
T1XX-FRT	mm	8:55:42	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	8:58:16	-0.006 OK	-0.004 OK	0.009
T1XX-FRT	mm	8:58:22	-0.009 OK	-0.005 OK	0.005
T1XX-FRT	mm	8:58:44	-0.005 OK	-0.004 OK	0.01
T1XX-FRT	mm	8:58:51	-0.006 OK	-0.003 OK	0.008
T1XX-FRT	mm	8:59:09	-0.007 OK	-0.005 OK	0.006
T1XX-FRT	mm	8:59:15	-0.005 OK	-0.003 OK	0.01
T1XX-FRT	mm	8:59:33	-0.007 OK	-0.004 OK	0.008
T1XX-FRT	mm	8:59:40	-0.009 OK	-0.004 OK	0.005
T1XX-FRT	mm	8:59:59	-0.009 OK	-0.005 OK	0.004
T1XX-FRT	mm	9:00:10	-0.007 OK	-0.001 OK	0.009
T1XX-FRT	mm	9:00:23	-0.01 OK	-0.005 OK	0.002
T1XX-FRT	mm	9:00:35	-0.002 OK	-0.005 OK	0.011
T1XX-FRT	mm	9:00:48	-0.005 OK	0 OK	0.009
T1XX-FRT	mm	9:00:55	-0.009 OK	-0.002 OK	0.006
T1XX-FRT	mm	9:01:13	-0.005 OK	-0.002 OK	0.01
T1XX-FRT	mm	9:01:20	-0.008 OK	-0.003 OK	0.006
T1XX-FRT	mm	9:01:39	-0.007 OK	-0.003 OK	0.008
T1XX-FRT	mm	9:01:46	-0.003 OK	-0.006 OK	0.011
T1XX-FRT	mm	9:02:03	0 OK	-0.003 OK	0.015
T1XX-FRT	mm	9:02:10	-0.002 OK	-0.003 OK	0.013
T1XX-FRT	mm	9:02:28	-0.007 OK	-0.003 OK	0.008
T1XX-FRT	mm	9:02:35	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	9:02:56	0 OK	-0.006 OK	0.013
T1XX-FRT	mm	9:03:03	-0.001 OK	-0.007 OK	0.012
T1XX-FRT	mm	9:03:19	-0.003 OK	-0.003 OK	0.012
T1XX-FRT	mm	9:03:30	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	9:03:44	-0.005 OK	-0.005 OK	0.008
T1XX-FRT	mm	9:03:55	-0.005 OK	-0.004 OK	0.009
T1XX-FRT	mm	9:04:08	-0.002 OK	-0.004 OK	0.012
T1XX-FRT	mm	9:04:15	-0.004 OK	0.003 OK	0.012
T1XX-FRT	mm	9:04:33	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	9:04:45	-0.006 OK	-0.003 OK	0.009

T1XX-FRT	mm	9:04:58	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	9:05:04	-0.004 OK	-0.003 OK	0.01
T1XX-FRT	mm	9:05:24	-0.009 OK	-0.003 OK	0.006
T1XX-FRT	mm	9:05:30	0.002 OK	-0.006 OK	0.015
T1XX-FRT	mm	9:05:48	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	9:05:54	-0.002 OK	-0.004 OK	0.011
T1XX-FRT	mm	9:06:14	0.001 OK	-0.004 OK	0.015
T1XX-FRT	mm	9:06:21	-0.005 OK	-0.003 OK	0.01
T1XX-FRT	mm	9:06:39	-0.006 OK	-0.003 OK	0.009
T1XX-FRT	mm	9:06:46	-0.006 OK	0.001 OK	0.01
T1XX-FRT	mm	9:07:05	-0.005 OK	-0.001 OK	0.01
T1XX-FRT	mm	9:07:11	-0.002 OK	0.001 OK	0.015
T1XX-FRT	mm	9:07:31	-0.008 OK	-0.003 OK	0.007
T1XX-FRT	mm	9:07:37	-0.006 OK	-0.004 OK	0.008
T1XX-FRT	mm	9:07:53	-0.001 OK	-0.005 OK	0.012
T1XX-FRT	mm	9:08:00	-0.005 OK	0.003 OK	0.011
T1XX-FRT	mm	9:08:20	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	9:08:27	0 OK	-0.005 OK	0.014
T1XX-FRT	mm	9:08:43	0.001 OK	-0.005 OK	0.014
T1XX-FRT	mm	9:08:50	-0.005 OK	-0.002 OK	0.01
T1XX-FRT	mm	9:09:09	-0.002 OK	-0.005 OK	0.012
T1XX-FRT	mm	9:09:15	-0.003 OK	-0.002 OK	0.012
T1XX-FRT	mm	9:09:34	-0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	9:09:40	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	9:10:01	-0.005 OK	-0.005 OK	0.008
T1XX-FRT	mm	9:10:07	-0.005 OK	0.001 OK	0.01
T1XX-FRT	mm	9:10:36	-0.005 OK	0.001 OK	0.01
T1XX-FRT	mm	9:10:45	-0.007 OK	-0.004 OK	0.006
T1XX-FRT	mm	9:10:51	-0.002 OK	-0.005 OK	0.012
T1XX-FRT	mm	9:11:19	-0.002 OK	-0.005 OK	0.012
T1XX-FRT	mm	9:11:37	-0.008 OK	0.003 OK	0.008
T1XX-FRT	mm	9:11:44	0.002 OK	-0.009 OK	0.013
T1XX-FRT	mm	9:12:14	-0.006 OK	-0.003 OK	0.008
T1XX-FRT	mm	9:12:21	-0.002 OK	-0.004 OK	0.012
T1XX-FRT	mm	9:12:42	-0.005 OK	-0.003 OK	0.01
T1XX-FRT	mm	9:12:48	-0.005 OK	0 OK	0.01
T1XX-FRT	mm	9:13:07	-0.004 OK	0.002 OK	0.011
T1XX-FRT	mm	9:13:14	0 OK	-0.003 OK	0.015
T1XX-FRT	mm	9:13:36	-0.006 OK	-0.002 OK	0.009
T1XX-FRT	mm	9:13:42	-0.005 OK	-0.004 OK	0.009
T1XX-FRT	mm	9:13:58	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	9:14:05	0.001 OK	-0.004 OK	0.015
T1XX-FRT	mm	9:14:31	-0.003 OK	-0.003 OK	0.01

T1XX-FRT	mm	9:14:37	-0.002 OK	-0.003 OK	0.013
T1XX-FRT	mm	9:15:08	-0.003 OK	-0.001 OK	0.013
T1XX-FRT	mm	9:15:15	0.001 OK	0 OK	0.017
T1XX-FRT	mm	9:15:34	-0.005 OK	-0.002 OK	0.009
T1XX-FRT	mm	9:15:41	-0.008 OK	0.004 OK	0.009
T1XX-FRT	mm	9:16:03	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	9:16:10	0.005 OK	-0.005 OK	0.019
T1XX-FRT	mm	9:16:38	-0.004 OK	-0.002 OK	0.011
T1XX-FRT	mm	9:16:44	0.005 OK	-0.005 OK	0.017
T1XX-FRT	mm	9:17:08	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	9:17:15	0.001 OK	0.006 OK	0.015
T1XX-FRT	mm	9:17:35	-0.004 OK	-0.004 OK	0.009
T1XX-FRT	mm	9:17:42	0 OK	-0.004 OK	0.014
T1XX-FRT	mm	9:18:09	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	9:18:15	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	9:18:36	-0.006 OK	-0.004 OK	0.008
T1XX-FRT	mm	9:18:43	-0.006 OK	-0.002 OK	0.008
T1XX-FRT	mm	9:19:03	-0.004 OK	-0.003 OK	0.01
T1XX-FRT	mm	9:19:10	-0.002 OK	-0.004 OK	0.012
T1XX-FRT	mm	9:19:30	-0.005 OK	0 OK	0.011
T1XX-FRT	mm	9:19:36	-0.007 OK	-0.003 OK	0.006
T1XX-FRT	mm	9:20:03	-0.008 OK	-0.001 OK	0.007
T1XX-FRT	mm	9:20:09	-0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	9:20:29	-0.007 OK	-0.004 OK	0.007
T1XX-FRT	mm	9:20:35	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	9:20:57	-0.008 OK	-0.002 OK	0.007
T1XX-FRT	mm	9:21:03	0.005 OK	-0.005 OK	0.015
T1XX-FRT	mm	9:21:25	-0.004 OK	-0.002 OK	0.011
T1XX-FRT	mm	9:21:48	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	9:21:56	-0.004 OK	-0.003 OK	0.01
T1XX-FRT	mm	9:22:02	-0.005 OK	-0.005 OK	0.008
T1XX-FRT	mm	9:22:27	-0.005 OK	-0.005 OK	0.008
T1XX-FRT	mm	9:22:37	-0.004 OK	-0.006 OK	0.01
T1XX-FRT	mm	9:22:43	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	9:23:03	-0.007 OK	-0.001 OK	0.007
T1XX-FRT	mm	9:23:21	-0.004 OK	0 OK	0.01
T1XX-FRT	mm	9:23:28	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	9:23:53	-0.004 OK	-0.004 OK	0.008
T1XX-FRT	mm	9:23:59	-0.008 OK	-0.003 OK	0.006
T1XX-FRT	mm	9:24:17	-0.007 OK	-0.003 OK	0.007
T1XX-FRT	mm	9:24:24	-0.006 OK	-0.002 OK	0.009
T1XX-FRT	mm	9:24:55	-0.008 OK	-0.003 OK	0.007
T1XX-FRT	mm	9:25:01	-0.004 OK	-0.002 OK	0.01

T1XX-FRT	mm	9:25:27	-0.004 OK	-0.002 OK	0.011
T1XX-FRT	mm	9:25:34	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	9:26:02	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	9:26:09	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	9:26:27	-0.007 OK	-0.002 OK	0.008
T1XX-FRT	mm	9:26:33	-0.004 OK	-0.004 OK	0.01
T1XX-FRT	mm	9:26:55	-0.007 OK	-0.003 OK	0.007
T1XX-FRT	mm	9:27:01	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	9:27:30	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	9:27:36	-0.002 OK	-0.004 OK	0.012
T1XX-FRT	mm	9:27:58	-0.002 OK	-0.006 OK	0.011
T1XX-FRT	mm	9:28:05	-0.006 OK	-0.003 OK	0.008
T1XX-FRT	mm	9:28:29	-0.006 OK	-0.002 OK	0.009
T1XX-FRT	mm	9:28:36	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	9:28:58	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	9:29:05	-0.005 OK	-0.004 OK	0.009
T1XX-FRT	mm	9:29:30	-0.006 OK	-0.004 OK	0.008
T1XX-FRT	mm	9:29:37	-0.004 OK	-0.004 OK	0.009
T1XX-FRT	mm	9:30:02	-0.004 OK	0.001 OK	0.012
T1XX-FRT	mm	9:30:08	-0.005 OK	-0.002 OK	0.009
T1XX-FRT	mm	9:30:30	-0.007 OK	-0.003 OK	0.007
T1XX-FRT	mm	9:30:37	-0.005 OK	-0.002 OK	0.01
T1XX-FRT	mm	9:31:08	-0.007 OK	-0.003 OK	0.006
T1XX-FRT	mm	9:31:19	-0.004 OK	-0.003 OK	0.01
T1XX-FRT	mm	9:31:32	-0.004 OK	-0.003 OK	0.011
T1XX-FRT	mm	9:31:39	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	9:32:37	0 OK	-0.001 OK	0.014
T1XX-FRT	mm	9:32:44	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	9:33:02	-0.003 OK	0.004 OK	0.015
T1XX-FRT	mm	9:33:29	-0.003 OK	0.004 OK	0.015
T1XX-FRT	mm	9:33:36	-0.003 OK	-0.001 OK	0.011
T1XX-FRT	mm	9:33:42	-0.005 OK	0 OK	0.009
T1XX-FRT	mm	9:34:00	-0.006 OK	0 OK	0.008
T1XX-FRT	mm	9:34:07	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	9:34:18	-0.004 OK	-0.003 OK	0.008
T1XX-FRT	mm	9:35:00	-0.004 OK	-0.003 OK	0.008
T1XX-FRT	mm	9:35:07	-0.004 OK	-0.005 OK	0.009
T1XX-FRT	mm	9:35:13	-0.006 OK	-0.003 OK	0.007
T1XX-FRT	mm	9:35:27	-0.008 OK	-0.003 OK	0.007
T1XX-FRT	mm	9:35:33	-0.005 OK	-0.005 OK	0.008
T1XX-FRT	mm	9:35:39	-0.005 OK	-0.004 OK	0.007
T1XX-FRT	mm	9:36:12	-0.005 OK	-0.004 OK	0.007
T1XX-FRT	mm	9:36:18	-0.004 OK	-0.003 OK	0.01

T1XX-FRT	mm	9:36:24	0.007 OK	-0.006 OK	0.018
T1XX-FRT	mm	9:45:10	-0.006 OK	-0.004 OK	0.006
T1XX-FRT	mm	9:45:16	-0.005 OK	-0.004 OK	0.009
T1XX-FRT	mm	9:45:35	0 OK	-0.006 OK	0.013
T1XX-FRT	mm	9:45:42	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	9:46:20	-0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	9:46:27	-0.004 OK	-0.004 OK	0.009
T1XX-FRT	mm	9:46:43	-0.008 OK	-0.003 OK	0.006
T1XX-FRT	mm	9:46:49	-0.007 OK	-0.004 OK	0.006
T1XX-FRT	mm	9:47:11	-0.009 OK	-0.004 OK	0.004
T1XX-FRT	mm	9:47:17	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	9:47:34	-0.003 OK	-0.004 OK	0.011
T1XX-FRT	mm	9:47:40	-0.006 OK	-0.003 OK	0.008
T1XX-FRT	mm	9:47:58	-0.003 OK	0.003 OK	0.012
T1XX-FRT	mm	9:48:05	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	9:48:29	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	9:49:00	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	9:49:07	-0.005 OK	-0.003 OK	0.01
T1XX-FRT	mm	9:49:14	-0.007 OK	-0.004 OK	0.007
T1XX-FRT	mm	9:49:31	-0.008 OK	-0.004 OK	0.006
T1XX-FRT	mm	9:49:43	-0.002 OK	-0.004 OK	0.012
T1XX-FRT	mm	9:50:04	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	9:50:11	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	9:50:31	-0.005 OK	-0.002 OK	0.009
T1XX-FRT	mm	9:50:38	0.003 OK	-0.009 OK	0.014
T1XX-FRT	mm	9:50:58	0.01 OK	-0.01 OK	0.02
T1XX-FRT	mm	9:51:05	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	9:51:24	-0.003 OK	-0.004 OK	0.01
T1XX-FRT	mm	9:51:31	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	9:51:51	-0.003 OK	-0.005 OK	0.009
T1XX-FRT	mm	9:51:57	0.007 OK	-0.007 OK	0.018
T1XX-FRT	mm	9:52:34	0.007 OK	-0.007 OK	0.018
T1XX-FRT	mm	9:52:43	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	9:52:50	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	9:53:44	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	9:53:50	-0.006 OK	-0.002 OK	0.008
T1XX-FRT	mm	9:54:03	0.002 OK	-0.006 OK	0.014
T1XX-FRT	mm	9:54:14	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	9:54:47	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	9:54:54	0.002 OK	-0.004 OK	0.015
T1XX-FRT	mm	9:55:27	0.002 OK	-0.004 OK	0.015
T1XX-FRT	mm	9:55:33	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	9:56:12	-0.004 OK	-0.002 OK	0.011

T1XX-FRT	mm	9:56:18	0.006 OK	-0.001 OK	0.021
T1XX-FRT	mm	9:56:32	0.001 OK	-0.004 OK	0.015
T1XX-FRT	mm	9:56:38	-0.004 OK	-0.003 OK	0.01
T1XX-FRT	mm	9:56:45	-0.006 OK	-0.003 OK	0.007
T1XX-FRT	mm	9:56:51	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	9:56:58	-0.006 OK	-0.003 OK	0.007
T1XX-FRT	mm	9:57:04	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	9:57:11	-0.003 OK	-0.004 OK	0.01
T1XX-FRT	mm	9:58:40	-0.003 OK	-0.004 OK	0.01
T1XX-FRT	mm	9:58:48	-0.004 OK	0.004 OK	0.01
T1XX-FRT	mm	9:58:55	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	9:59:12	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	9:59:18	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	9:59:54	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:00:00	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	10:00:07	-0.005 OK	0.002 OK	0.009
T1XX-FRT	mm	10:00:20	-0.004 OK	-0.003 OK	0.008
T1XX-FRT	mm	10:00:27	-0.004 OK	-0.002 OK	0.009
T1XX-FRT	mm	10:00:33	-0.005 OK	-0.005 OK	0.007
T1XX-FRT	mm	10:00:40	-0.004 OK	-0.002 OK	0.008
T1XX-FRT	mm	10:00:46	-0.003 OK	-0.004 OK	0.01
T1XX-FRT	mm	10:01:35	-0.003 OK	-0.004 OK	0.01
T1XX-FRT	mm	10:01:42	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	10:01:48	-0.004 OK	0.006 OK	0.011
T1XX-FRT	mm	10:02:30	-0.005 OK	-0.003 OK	0.007
T1XX-FRT	mm	10:02:37	-0.004 OK	-0.003 OK	0.008
T1XX-FRT	mm	10:02:44	-0.007 OK	-0.004 OK	0.005
T1XX-FRT	mm	10:02:50	-0.005 OK	0.004 OK	0.013
T1XX-FRT	mm	10:02:57	0.001 OK	-0.005 OK	0.014
T1XX-FRT	mm	10:03:03	-0.006 OK	0.002 OK	0.008
T1XX-FRT	mm	10:03:10	-0.004 OK	-0.004 OK	0.008
T1XX-FRT	mm	10:03:16	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	10:03:28	-0.007 OK	-0.005 OK	0.004
T1XX-FRT	mm	10:03:35	-0.002 OK	0.004 OK	0.015
T1XX-FRT	mm	10:04:05	-0.006 OK	-0.004 OK	0.007
T1XX-FRT	mm	10:04:12	-0.002 OK	-0.006 OK	0.009
T1XX-FRT	mm	10:04:29	-0.004 OK	-0.004 OK	0.009
T1XX-FRT	mm	10:04:36	-0.003 OK	-0.001 OK	0.011
T1XX-FRT	mm	10:05:03	0.004 OK	-0.003 OK	0.016
T1XX-FRT	mm	10:07:30	0.004 OK	-0.003 OK	0.016
T1XX-FRT	mm	10:07:41	-0.005 OK	0 OK	0.009
T1XX-FRT	mm	10:07:47	0.008 OK	-0.01 OK	0.018
T1XX-FRT	mm	10:09:07	-0.006 OK	-0.005 OK	0.007

T1XX-FRT	mm	10:12:54	-0.006 OK	-0.005 OK	0.007
T1XX-FRT	mm	10:13:00	-0.007 OK	0.003 OK	0.008
T1XX-FRT	mm	10:13:20	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	10:13:26	-0.007 OK	-0.001 OK	0.006
T1XX-FRT	mm	10:15:36	-0.007 OK	-0.001 OK	0.006
T1XX-FRT	mm	10:15:43	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	10:15:49	-0.006 OK	-0.006 OK	0.005
T1XX-FRT	mm	10:16:03	-0.006 OK	-0.003 OK	0.008
T1XX-FRT	mm	10:16:09	-0.008 OK	-0.003 OK	0.006
T1XX-FRT	mm	10:16:15	-0.009 OK	-0.003 OK	0.005
T1XX-FRT	mm	10:16:22	0.001 OK	0.006 OK	0.015
T1XX-FRT	mm	10:16:29	-0.003 OK	-0.004 OK	0.01
T1XX-FRT	mm	10:16:35	-0.002 OK	-0.004 OK	0.011
T1XX-FRT	mm	10:16:42	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	10:16:48	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	10:16:55	-0.002 OK	-0.004 OK	0.011
T1XX-FRT	mm	10:17:01	-0.007 OK	0.001 OK	0.008
T1XX-FRT	mm	10:17:08	-0.008 OK	-0.004 OK	0.004
T1XX-FRT	mm	10:17:15	-0.003 OK	-0.001 OK	0.012
T1XX-FRT	mm	10:17:21	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:18:00	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:18:07	-0.008 OK	-0.004 OK	0.005
T1XX-FRT	mm	10:18:13	-0.006 OK	-0.003 OK	0.007
T1XX-FRT	mm	10:18:27	-0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	10:18:33	-0.004 OK	-0.004 OK	0.008
T1XX-FRT	mm	10:18:40	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	10:19:20	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	10:19:27	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	10:19:33	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:19:46	-0.001 OK	-0.005 OK	0.011
T1XX-FRT	mm	10:19:58	-0.005 OK	-0.001 OK	0.009
T1XX-FRT	mm	10:20:04	-0.005 OK	-0.002 OK	0.008
T1XX-FRT	mm	10:20:34	-0.005 OK	-0.002 OK	0.008
T1XX-FRT	mm	10:20:40	-0.003 OK	0.002 OK	0.013
T1XX-FRT	mm	10:20:47	-0.005 OK	-0.002 OK	0.01
T1XX-FRT	mm	10:21:05	-0.005 OK	-0.003 OK	0.007
T1XX-FRT	mm	10:21:12	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	10:21:23	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	10:21:34	0.004 OK	-0.005 OK	0.017
T1XX-FRT	mm	10:21:46	0.004 OK	-0.01 OK	0.014
T1XX-FRT	mm	10:21:57	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	10:22:04	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	10:22:10	0 OK	-0.002 OK	0.014

T1XX-FRT	mm	10:22:22	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	10:22:28	0 OK	-0.003 OK	0.015
T1XX-FRT	mm	10:22:35	-0.005 OK	0.001 OK	0.009
T1XX-FRT	mm	10:22:42	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:22:48	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	10:23:00	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	10:23:12	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:23:18	0.001 OK	-0.005 OK	0.013
T1XX-FRT	mm	10:23:39	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	10:24:14	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	10:24:20	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	10:24:27	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	10:24:39	-0.009 OK	-0.004 OK	0.005
T1XX-FRT	mm	10:25:18	-0.009 OK	-0.004 OK	0.005
T1XX-FRT	mm	10:25:29	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	10:25:35	-0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	10:25:48	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	10:25:55	-0.006 OK	0.002 OK	0.009
T1XX-FRT	mm	10:26:02	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	10:26:08	-0.005 OK	-0.003 OK	0.007
T1XX-FRT	mm	10:26:15	-0.005 OK	-0.005 OK	0.007
T1XX-FRT	mm	10:26:26	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	10:26:33	0.004 OK	0.004 OK	0.018
T1XX-FRT	mm	10:26:39	-0.008 OK	0.002 OK	0.006
T1XX-FRT	mm	10:26:57	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	10:27:04	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	10:27:24	-0.001 OK	0.004 OK	0.016
T1XX-FRT	mm	10:28:03	-0.001 OK	0.004 OK	0.016
T1XX-FRT	mm	10:28:09	0.002 OK	-0.004 OK	0.016
T1XX-FRT	mm	10:28:16	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:28:34	-0.007 OK	-0.004 OK	0.005
T1XX-FRT	mm	10:28:45	0.008 OK	-0.006 OK	0.02
T1XX-FRT	mm	10:28:52	0.01 OK	-0.01 OK	0.02
T1XX-FRT	mm	10:29:09	0.01 OK	-0.01 OK	0.02
T1XX-FRT	mm	10:29:15	-0.009 OK	-0.004 OK	0.004
T1XX-FRT	mm	10:29:22	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	10:29:33	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	10:29:40	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	10:29:51	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	10:29:58	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	10:30:09	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	10:30:18	-0.004 OK	-0.005 OK	0.009
T1XX-FRT	mm	10:30:25	-0.007 OK	-0.001 OK	0.009

T1XX-FRT	mm	10:30:42	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	10:30:48	-0.002 OK	-0.002 OK	0.014
T1XX-FRT	mm	10:31:08	-0.004 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:31:20	-0.006 OK	-0.003 OK	0.01
T1XX-FRT	mm	10:31:32	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:31:39	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	10:32:00	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	10:32:06	-0.005 OK	-0.001 OK	0.009
T1XX-FRT	mm	10:32:24	-0.008 OK	0.005 OK	0.008
T1XX-FRT	mm	10:33:04	-0.008 OK	0.005 OK	0.008
T1XX-FRT	mm	10:33:10	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	10:33:17	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	10:33:30	-0.001 OK	-0.006 OK	0.011
T1XX-FRT	mm	10:33:36	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:33:43	0.004 OK	-0.004 OK	0.018
T1XX-FRT	mm	10:33:49	0 OK	0.001 OK	0.015
T1XX-FRT	mm	10:34:04	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	10:34:16	-0.005 OK	0 OK	0.01
T1XX-FRT	mm	10:34:28	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	10:34:40	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	10:34:51	-0.004 OK	-0.006 OK	0.008
T1XX-FRT	mm	10:34:58	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	10:35:39	-0.007 OK	-0.002 OK	0.008
T1XX-FRT	mm	10:35:45	-0.004 OK	0.007 OK	0.013
T1XX-FRT	mm	10:35:52	-0.005 OK	0.005 OK	0.012
T1XX-FRT	mm	10:36:03	-0.005 OK	-0.002 OK	0.009
T1XX-FRT	mm	10:36:10	-0.005 OK	-0.003 OK	0.01
T1XX-FRT	mm	10:36:16	-0.004 OK	-0.002 OK	0.009
T1XX-FRT	mm	10:36:36	-0.003 OK	-0.004 OK	0.009
T1XX-FRT	mm	10:36:43	0.005 OK	-0.005 OK	0.018
T1XX-FRT	mm	10:36:57	-0.003 OK	-0.003 OK	0.012
T1XX-FRT	mm	10:37:04	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	10:37:22	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	10:37:29	0.005 OK	-0.003 OK	0.018
T1XX-FRT	mm	10:37:49	0.002 OK	-0.006 OK	0.015
T1XX-FRT	mm	10:37:55	-0.006 OK	-0.002 OK	0.009
T1XX-FRT	mm	10:38:17	-0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	10:38:29	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:38:42	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	10:38:54	-0.006 OK	-0.003 OK	0.008
T1XX-FRT	mm	10:39:06	-0.002 OK	-0.004 OK	0.011
T1XX-FRT	mm	10:39:12	-0.004 OK	-0.001 OK	0.011
T1XX-FRT	mm	10:39:32	-0.004 OK	-0.002 OK	0.011

T1XX-FRT	mm	10:39:39	-0.002 OK	0 OK	0.013
T1XX-FRT	mm	10:39:56	-0.001 OK	-0.002 OK	0.011
T1XX-FRT	mm	10:40:02	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	10:40:24	0 OK	-0.001 OK	0.015
T1XX-FRT	mm	10:40:30	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	10:40:53	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	10:41:00	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	10:41:21	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	10:41:27	0 OK	0 OK	0.016
T1XX-FRT	mm	10:41:57	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	10:42:03	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	10:42:22	0.003 OK	-0.002 OK	0.018
T1XX-FRT	mm	10:42:33	0 OK	-0.002 OK	0.015
T1XX-FRT	mm	10:42:50	-0.001 OK	0.001 OK	0.014
T1XX-FRT	mm	10:43:01	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	10:43:17	-0.001 OK	-0.005 OK	0.012
T1XX-FRT	mm	10:43:27	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	10:43:53	0.008 OK	-0.006 OK	0.019
T1XX-FRT	mm	10:44:27	0.008 OK	-0.006 OK	0.019
T1XX-FRT	mm	10:44:33	0.003 OK	-0.004 OK	0.016
T1XX-FRT	mm	10:44:39	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	10:45:02	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	10:45:09	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	10:45:16	0.005 OK	-0.003 OK	0.016
T1XX-FRT	mm	10:45:23	0.004 OK	-0.003 OK	0.018
T1XX-FRT	mm	10:45:51	0.003 OK	-0.004 OK	0.016
T1XX-FRT	mm	10:45:57	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	10:46:15	-0.005 OK	-0.001 OK	0.009
T1XX-FRT	mm	10:46:21	0.007 OK	-0.008 OK	0.019
T1XX-FRT	mm	10:46:42	0.001 OK	-0.001 OK	0.014
T1XX-FRT	mm	10:47:58	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	10:48:07	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	10:48:14	0.001 OK	-0.002 OK	0.016
T1XX-FRT	mm	10:48:24	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	10:48:37	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	10:48:43	-0.004 OK	0.001 OK	0.011
T1XX-FRT	mm	10:48:50	-0.002 OK	-0.004 OK	0.012
T1XX-FRT	mm	10:48:57	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	10:49:08	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	10:49:26	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	10:49:32	-0.002 OK	0.004 OK	0.014
T1XX-FRT	mm	10:49:52	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	10:50:04	0 OK	-0.002 OK	0.014

T1XX-FRT	mm	10:50:20	-0.001 OK	0.002 OK	0.016
T1XX-FRT	mm	10:50:27	0.001 OK	-0.004 OK	0.015
T1XX-FRT	mm	10:51:00	0.001 OK	-0.004 OK	0.015
T1XX-FRT	mm	10:51:10	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	10:51:16	0.006 OK	-0.006 OK	0.02
T1XX-FRT	mm	10:51:42	0 OK	0 OK	0.015
T1XX-FRT	mm	10:51:58	-0.001 OK	0.002 OK	0.015
T1XX-FRT	mm	10:52:05	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	10:52:32	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	10:52:42	-0.001 OK	-0.004 OK	0.012
T1XX-FRT	mm	10:52:48	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	10:53:04	-0.003 OK	-0.002 OK	0.012
T1XX-FRT	mm	10:53:25	-0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	10:53:31	-0.006 OK	-0.004 OK	0.007
T1XX-FRT	mm	10:53:52	0.006 OK	-0.007 OK	0.018
T1XX-FRT	mm	10:54:04	0.006 OK	-0.007 OK	0.019
T1XX-FRT	mm	10:54:25	0.007 OK	-0.005 OK	0.018
T1XX-FRT	mm	10:54:32	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	10:54:53	0 OK	0.003 OK	0.015
T1XX-FRT	mm	10:55:04	0.001 OK	-0.002 OK	0.016
T1XX-FRT	mm	10:58:00	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	10:58:12	0.001 OK	0.001 OK	0.018
T1XX-FRT	mm	11:00:12	-0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	11:00:23	-0.003 OK	0 OK	0.011
T1XX-FRT	mm	11:00:39	0 OK	-0.001 OK	0.014
T1XX-FRT	mm	11:02:26	0 OK	-0.001 OK	0.014
T1XX-FRT	mm	11:02:56	0 OK	-0.001 OK	0.014
T1XX-FRT	mm	11:03:03	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	11:03:10	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	11:03:22	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	11:03:35	-0.002 OK	0.003 OK	0.016
T1XX-FRT	mm	11:03:41	-0.004 OK	-0.003 OK	0.01
T1XX-FRT	mm	11:03:47	-0.006 OK	-0.004 OK	0.007
T1XX-FRT	mm	11:04:37	-0.006 OK	-0.004 OK	0.007
T1XX-FRT	mm	11:04:43	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	11:04:50	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	11:05:03	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	11:05:10	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	11:05:44	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	11:05:51	0.006 OK	-0.004 OK	0.019
T1XX-FRT	mm	11:05:57	0.004 OK	-0.005 OK	0.018
T1XX-FRT	mm	11:06:15	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	11:06:26	0 OK	-0.004 OK	0.013

T1XX-FRT	mm	11:06:57	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	11:07:03	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	11:07:10	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	11:08:08	0 OK	-0.005 OK	0.012
T1XX-FRT	mm	11:08:27	0 OK	-0.005 OK	0.012
T1XX-FRT	mm	11:08:34	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	11:08:58	0.003 OK	-0.003 OK	0.017
T1XX-FRT	mm	11:09:09	-0.001 OK	0.002 OK	0.014
T1XX-FRT	mm	11:09:21	0.007 OK	-0.005 OK	0.02
T1XX-FRT	mm	11:09:32	0.003 OK	-0.006 OK	0.015
T1XX-FRT	mm	11:09:44	-0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	11:09:50	0.007 OK	-0.003 OK	0.021
T1XX-FRT	mm	11:09:57	0.01 OK	0.002 OK	0.023
T1XX-FRT	mm	11:10:30	0.01 OK	0.002 OK	0.023
T1XX-FRT	mm	11:10:36	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	11:10:42	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	11:11:01	-0.003 OK	-0.004 OK	0.01
T1XX-FRT	mm	11:11:12	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:11:18	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	11:11:25	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	11:11:36	0.008 OK	-0.006 OK	0.019
T1XX-FRT	mm	11:12:00	-0.001 OK	-0.005 OK	0.011
T1XX-FRT	mm	11:12:12	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	11:12:24	0.01 OK	-0.006 OK	0.022
T1XX-FRT	mm	11:12:35	0.004 OK	0 OK	0.02
T1XX-FRT	mm	11:12:53	0 OK	-0.001 OK	0.015
T1XX-FRT	mm	11:13:00	0.006 OK	-0.001 OK	0.021
T1XX-FRT	mm	11:13:25	0.005 OK	-0.002 OK	0.019
T1XX-FRT	mm	11:13:36	0.001 OK	-0.003 OK	0.016
T1XX-FRT	mm	11:13:57	0.009 OK	-0.005 OK	0.021
T1XX-FRT	mm	11:14:03	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	11:14:27	0.006 OK	-0.005 OK	0.019
T1XX-FRT	mm	11:14:34	0.002 OK	-0.001 OK	0.017
T1XX-FRT	mm	11:15:02	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	11:15:08	0.001 OK	0 OK	0.016
T1XX-FRT	mm	11:15:28	0.002 OK	-0.001 OK	0.016
T1XX-FRT	mm	11:15:39	0 OK	-0.004 OK	0.014
T1XX-FRT	mm	11:16:04	0.002 OK	-0.001 OK	0.016
T1XX-FRT	mm	11:16:10	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:16:30	0.008 OK	0 OK	0.022
T1XX-FRT	mm	11:16:41	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	11:17:00	0.002 OK	-0.002 OK	0.017
T1XX-FRT	mm	11:17:12	0.002 OK	-0.002 OK	0.016

T1XX-FRT	mm	11:17:23	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	11:17:30	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	11:17:48	0 OK	-0.002 OK	0.015
T1XX-FRT	mm	11:18:00	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	11:18:14	0.003 OK	-0.003 OK	0.017
T1XX-FRT	mm	11:18:21	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:18:47	0.004 OK	-0.004 OK	0.017
T1XX-FRT	mm	11:18:58	0.005 OK	-0.001 OK	0.02
T1XX-FRT	mm	11:19:15	0 OK	0.001 OK	0.015
T1XX-FRT	mm	11:19:27	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	11:21:25	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	11:21:35	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	11:21:41	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	11:22:16	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	11:22:29	-0.005 OK	-0.001 OK	0.01
T1XX-FRT	mm	11:22:47	-0.004 OK	-0.004 OK	0.01
T1XX-FRT	mm	11:22:58	-0.005 OK	-0.003 OK	0.01
T1XX-FRT	mm	11:23:05	-0.005 OK	-0.002 OK	0.01
T1XX-FRT	mm	11:23:11	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:23:23	-0.005 OK	-0.004 OK	0.008
T1XX-FRT	mm	11:23:29	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	11:23:40	0.002 OK	0.001 OK	0.018
T1XX-FRT	mm	11:23:52	-0.005 OK	-0.004 OK	0.008
T1XX-FRT	mm	11:24:24	-0.005 OK	-0.004 OK	0.008
T1XX-FRT	mm	11:24:35	-0.003 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:24:41	-0.006 OK	-0.003 OK	0.008
T1XX-FRT	mm	11:25:04	-0.003 OK	-0.003 OK	0.009
T1XX-FRT	mm	11:25:11	-0.004 OK	0.004 OK	0.011
T1XX-FRT	mm	11:26:37	-0.004 OK	-0.003 OK	0.01
T1XX-FRT	mm	11:26:44	0.001 OK	-0.005 OK	0.014
T1XX-FRT	mm	11:27:32	0 OK	0.006 OK	0.019
T1XX-FRT	mm	11:27:39	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	11:28:17	0 OK	-0.004 OK	0.014
T1XX-FRT	mm	11:28:28	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:29:02	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	11:29:13	0.006 OK	-0.005 OK	0.019
T1XX-FRT	mm	11:29:37	-0.002 OK	-0.004 OK	0.012
T1XX-FRT	mm	11:29:44	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:30:12	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:30:24	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	11:30:51	-0.003 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:31:03	-0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	11:31:37	-0.002 OK	-0.002 OK	0.013

T1XX-FRT	mm	11:31:48	0.007 OK	-0.006 OK	0.019
T1XX-FRT	mm	11:31:55	-0.002 OK	0.003 OK	0.013
T1XX-FRT	mm	11:32:01	0.005 OK	-0.006 OK	0.017
T1XX-FRT	mm	11:32:12	0.006 OK	-0.005 OK	0.019
T1XX-FRT	mm	11:32:26	0.001 OK	-0.001 OK	0.016
T1XX-FRT	mm	11:32:37	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	11:33:09	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	11:33:19	0.001 OK	-0.002 OK	0.017
T1XX-FRT	mm	11:34:03	0.001 OK	-0.002 OK	0.017
T1XX-FRT	mm	11:34:10	0.014 NG	-0.007 OK	0.025
T1XX-FRT	mm	11:34:33	-0.001 OK	0 OK	0.013
T1XX-FRT	mm	11:34:45	-0.002 OK	0.001 OK	0.013
T1XX-FRT	mm	11:34:57	0.006 OK	-0.006 OK	0.018
T1XX-FRT	mm	11:35:08	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	11:35:28	0.005 OK	-0.005 OK	0.017
T1XX-FRT	mm	11:35:39	0.004 OK	-0.003 OK	0.019
T1XX-FRT	mm	11:35:56	0.003 OK	-0.003 OK	0.017
T1XX-FRT	mm	11:36:21	0.003 OK	-0.003 OK	0.017
T1XX-FRT	mm	11:36:27	0.006 OK	-0.003 OK	0.021
T1XX-FRT	mm	11:36:34	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	11:37:01	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	11:37:12	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	11:37:32	0.004 OK	-0.002 OK	0.019
T1XX-FRT	mm	11:37:39	0.005 OK	-0.001 OK	0.02
T1XX-FRT	mm	11:38:00	0.002 OK	-0.003 OK	0.014
T1XX-FRT	mm	11:38:06	-0.002 OK	-0.001 OK	0.013
T1XX-FRT	mm	11:38:35	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	11:38:41	0.007 OK	-0.008 OK	0.018
T1XX-FRT	mm	11:39:11	-0.001 OK	-0.005 OK	0.011
T1XX-FRT	mm	11:39:18	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	11:40:13	0 OK	-0.004 OK	0.012
T1XX-FRT	mm	11:40:24	0.004 OK	-0.004 OK	0.017
T1XX-FRT	mm	11:40:42	0.003 OK	-0.004 OK	0.017
T1XX-FRT	mm	11:40:54	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	11:41:07	0.001 OK	-0.002 OK	0.016
T1XX-FRT	mm	11:41:14	-0.006 OK	0.005 OK	0.011
T1XX-FRT	mm	11:41:31	0.001 OK	-0.002 OK	0.016
T1XX-FRT	mm	11:41:43	-0.001 OK	-0.001 OK	0.014
T1XX-FRT	mm	11:41:57	0.003 OK	-0.005 OK	0.016
T1XX-FRT	mm	11:42:08	-0.005 OK	-0.002 OK	0.01
T1XX-FRT	mm	11:42:21	-0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	11:42:33	-0.001 OK	0.003 OK	0.014
T1XX-FRT	mm	11:42:47	-0.001 OK	-0.002 OK	0.014

T1XX-FRT	mm	11:42:59	-0.003 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:43:15	-0.002 OK	-0.005 OK	0.01
T1XX-FRT	mm	11:43:26	0.005 OK	-0.005 OK	0.018
T1XX-FRT	mm	11:43:41	0.001 OK	-0.002 OK	0.016
T1XX-FRT	mm	11:43:52	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	11:44:12	0.008 OK	-0.004 OK	0.02
T1XX-FRT	mm	11:44:24	0.01 OK	-0.006 OK	0.021
T1XX-FRT	mm	11:44:37	0.003 OK	-0.003 OK	0.017
T1XX-FRT	mm	11:44:48	0.006 OK	0 OK	0.021
T1XX-FRT	mm	11:45:13	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	11:45:24	0.004 OK	-0.002 OK	0.019
T1XX-FRT	mm	11:45:37	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	11:45:43	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	11:46:12	0.006 OK	-0.006 OK	0.018
T1XX-FRT	mm	11:46:18	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	11:46:39	0.004 OK	-0.002 OK	0.017
T1XX-FRT	mm	11:46:51	0.001 OK	-0.001 OK	0.016
T1XX-FRT	mm	11:47:39	0.001 OK	-0.001 OK	0.016
T1XX-FRT	mm	11:47:46	-0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	11:47:52	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	11:47:58	-0.003 OK	-0.001 OK	0.012
T1XX-FRT	mm	11:48:05	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	11:48:12	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	11:48:19	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	11:48:34	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	11:48:46	-0.002 OK	0.001 OK	0.012
T1XX-FRT	mm	11:49:08	0.003 OK	-0.003 OK	0.018
T1XX-FRT	mm	11:49:15	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	11:49:34	-0.002 OK	0.003 OK	0.016
T1XX-FRT	mm	11:49:41	0 OK	0.003 OK	0.017
T1XX-FRT	mm	11:50:04	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:50:10	0.008 OK	-0.001 OK	0.023
T1XX-FRT	mm	11:50:34	0.005 OK	-0.005 OK	0.018
T1XX-FRT	mm	11:50:45	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:51:04	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:51:16	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	11:51:34	0.002 OK	-0.004 OK	0.016
T1XX-FRT	mm	11:51:41	0.006 OK	-0.002 OK	0.019
T1XX-FRT	mm	11:52:30	0.006 OK	-0.002 OK	0.019
T1XX-FRT	mm	11:52:40	0 OK	-0.003 OK	0.015
T1XX-FRT	mm	11:52:46	0.003 OK	-0.002 OK	0.017
T1XX-FRT	mm	11:52:59	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	11:53:10	-0.004 OK	-0.002 OK	0.011

T1XX-FRT	mm	11:53:16	0.005 OK	-0.005 OK	0.018
T1XX-FRT	mm	11:53:35	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	11:53:42	0.007 OK	-0.003 OK	0.019
T1XX-FRT	mm	11:53:58	-0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	11:54:10	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	11:54:28	0.002 OK	-0.002 OK	0.014
T1XX-FRT	mm	11:54:39	0.003 OK	-0.004 OK	0.016
T1XX-FRT	mm	11:55:04	-0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	11:55:57	-0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	11:56:03	0 OK	-0.001 OK	0.014
T1XX-FRT	mm	11:56:10	-0.004 OK	-0.002 OK	0.011
T1XX-FRT	mm	11:56:32	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	11:56:44	-0.004 OK	0.001 OK	0.012
T1XX-FRT	mm	11:56:56	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	11:57:08	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	11:57:14	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:57:25	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	11:57:32	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	11:57:43	0.008 OK	-0.008 OK	0.018
T1XX-FRT	mm	11:57:55	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:58:02	0.01 OK	-0.01 OK	0.02
T1XX-FRT	mm	11:58:14	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	11:58:34	-0.002 OK	-0.005 OK	0.01
T1XX-FRT	mm	11:58:45	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	11:59:09	0.009 OK	0.001 OK	0.02
T1XX-FRT	mm	11:59:20	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	11:59:47	0.009 OK	-0.005 OK	0.021
T1XX-FRT	mm	11:59:59	-0.003 OK	-0.004 OK	0.011
T1XX-FRT	mm	12:00:18	0.009 OK	-0.01 OK	0.019
T1XX-FRT	mm	12:00:29	0.007 OK	-0.001 OK	0.019
T1XX-FRT	mm	12:01:22	0.007 OK	-0.001 OK	0.019
T1XX-FRT	mm	12:01:30	0.005 OK	-0.005 OK	0.018
T1XX-FRT	mm	12:01:36	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	12:01:43	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	12:01:50	0.007 OK	0.004 OK	0.022
T1XX-FRT	mm	12:01:56	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:02:03	0.003 OK	0.003 OK	0.021
T1XX-FRT	mm	12:02:25	0.004 OK	-0.001 OK	0.017
T1XX-FRT	mm	12:02:36	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	12:02:54	-0.003 OK	-0.004 OK	0.01
T1XX-FRT	mm	12:03:25	-0.003 OK	-0.004 OK	0.01
T1XX-FRT	mm	12:03:32	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	12:03:38	0.004 OK	-0.004 OK	0.016

T1XX-FRT	mm	12:04:39	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	12:04:45	0.004 OK	-0.003 OK	0.016
T1XX-FRT	mm	12:05:04	-0.005 OK	-0.004 OK	0.007
T1XX-FRT	mm	12:05:15	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	12:05:26	0.004 OK	-0.007 OK	0.015
T1XX-FRT	mm	12:05:40	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	12:05:52	-0.002 OK	0.005 OK	0.013
T1XX-FRT	mm	12:06:10	0.001 OK	-0.001 OK	0.015
T1XX-FRT	mm	12:06:21	0.004 OK	-0.003 OK	0.018
T1XX-FRT	mm	12:06:42	0.001 OK	-0.002 OK	0.016
T1XX-FRT	mm	12:06:54	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	12:07:16	0.003 OK	-0.006 OK	0.015
T1XX-FRT	mm	12:07:22	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	12:09:14	-0.002 OK	0.002 OK	0.014
T1XX-FRT	mm	12:09:23	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	12:09:30	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	12:09:36	-0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	12:09:43	-0.004 OK	0.003 OK	0.011
T1XX-FRT	mm	12:09:50	-0.001 OK	-0.002 OK	0.011
T1XX-FRT	mm	12:09:56	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	12:10:33	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	12:10:39	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:10:46	-0.001 OK	0.005 OK	0.018
T1XX-FRT	mm	12:11:22	-0.001 OK	0.005 OK	0.018
T1XX-FRT	mm	12:12:11	0.001 OK	-0.005 OK	0.014
T1XX-FRT	mm	12:12:30	-0.003 OK	0.005 OK	0.016
T1XX-FRT	mm	12:12:37	-0.003 OK	-0.001 OK	0.011
T1XX-FRT	mm	12:12:43	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	12:12:50	-0.005 OK	0.003 OK	0.01
T1XX-FRT	mm	12:12:56	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:14:00	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:14:07	-0.003 OK	-0.001 OK	0.012
T1XX-FRT	mm	12:14:34	-0.003 OK	-0.001 OK	0.012
T1XX-FRT	mm	12:14:40	0.006 OK	-0.003 OK	0.019
T1XX-FRT	mm	12:15:00	-0.007 OK	0.003 OK	0.009
T1XX-FRT	mm	12:15:06	-0.003 OK	0.002 OK	0.011
T1XX-FRT	mm	12:15:13	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	12:15:19	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	12:15:26	-0.004 OK	-0.002 OK	0.008
T1XX-FRT	mm	12:15:32	-0.006 OK	-0.003 OK	0.007
T1XX-FRT	mm	12:15:43	-0.004 OK	0.004 OK	0.01
T1XX-FRT	mm	12:15:50	0 OK	-0.001 OK	0.014
T1XX-FRT	mm	12:15:57	-0.002 OK	0.002 OK	0.013

T1XX-FRT	mm	12:16:03	0.001 OK	-0.007 OK	0.012
T1XX-FRT	mm	12:16:10	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	12:16:17	0.003 OK	-0.004 OK	0.015
T1XX-FRT	mm	12:16:30	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	12:16:42	0.001 OK	-0.001 OK	0.013
T1XX-FRT	mm	12:17:07	0.003 OK	-0.006 OK	0.014
T1XX-FRT	mm	12:17:14	0.004 OK	-0.006 OK	0.015
T1XX-FRT	mm	12:18:27	0.004 OK	-0.004 OK	0.015
T1XX-FRT	mm	12:18:33	0.003 OK	0.004 OK	0.02
T1XX-FRT	mm	12:18:56	0.001 OK	0.004 OK	0.014
T1XX-FRT	mm	12:19:07	0.001 OK	0.004 OK	0.016
T1XX-FRT	mm	12:19:23	0.002 OK	-0.003 OK	0.013
T1XX-FRT	mm	12:19:29	0.002 OK	-0.003 OK	0.014
T1XX-FRT	mm	12:19:48	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	12:19:55	-0.004 OK	-0.002 OK	0.009
T1XX-FRT	mm	12:20:13	0.008 OK	-0.009 OK	0.018
T1XX-FRT	mm	12:20:20	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	12:20:41	0 OK	0.006 OK	0.019
T1XX-FRT	mm	12:20:48	-0.001 OK	-0.006 OK	0.012
T1XX-FRT	mm	12:21:05	0 OK	0.001 OK	0.013
T1XX-FRT	mm	12:21:11	0.005 OK	0.003 OK	0.019
T1XX-FRT	mm	12:21:29	0.006 OK	-0.003 OK	0.019
T1XX-FRT	mm	12:21:35	0 OK	-0.004 OK	0.012
T1XX-FRT	mm	12:21:54	0.003 OK	0.001 OK	0.017
T1XX-FRT	mm	12:22:06	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	12:22:20	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	12:22:27	0.002 OK	-0.004 OK	0.015
T1XX-FRT	mm	12:22:50	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	12:22:56	0 OK	0.006 OK	0.019
T1XX-FRT	mm	12:23:19	0.004 OK	-0.005 OK	0.016
T1XX-FRT	mm	12:23:25	0.002 OK	-0.005 OK	0.014
T1XX-FRT	mm	12:23:54	-0.004 OK	0.003 OK	0.011
T1XX-FRT	mm	12:24:04	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	12:24:24	0.008 OK	-0.009 OK	0.017
T1XX-FRT	mm	12:24:31	0.014 NG	-0.005 OK	0.024
T1XX-FRT	mm	12:24:56	0.004 OK	-0.004 OK	0.017
T1XX-FRT	mm	12:25:59	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:26:08	0.01 OK	-0.006 OK	0.019
T1XX-FRT	mm	12:26:14	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	12:26:26	-0.004 OK	0 OK	0.01
T1XX-FRT	mm	12:26:32	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	12:26:39	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	12:26:45	-0.004 OK	-0.005 OK	0.009

T1XX-FRT	mm	12:27:00	-0.004 OK	-0.004 OK	0.009
T1XX-FRT	mm	12:27:07	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	12:27:30	-0.005 OK	0.001 OK	0.008
T1XX-FRT	mm	12:27:42	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	12:28:00	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	12:28:07	-0.007 OK	-0.003 OK	0.005
T1XX-FRT	mm	12:28:32	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	12:28:44	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	12:29:02	-0.001 OK	0.006 OK	0.013
T1XX-FRT	mm	12:29:09	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	12:29:36	0 OK	-0.004 OK	0.012
T1XX-FRT	mm	12:29:48	0.002 OK	-0.006 OK	0.013
T1XX-FRT	mm	12:30:08	0.007 OK	-0.009 OK	0.016
T1XX-FRT	mm	12:30:14	0.003 OK	-0.004 OK	0.015
T1XX-FRT	mm	12:30:41	-0.004 OK	-0.003 OK	0.008
T1XX-FRT	mm	12:30:48	0.006 OK	-0.007 OK	0.016
T1XX-FRT	mm	12:31:16	0.006 OK	-0.007 OK	0.016
T1XX-FRT	mm	12:31:26	0.007 OK	-0.01 OK	0.016
T1XX-FRT	mm	12:31:32	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	12:31:54	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	12:32:12	-0.004 OK	-0.004 OK	0.007
T1XX-FRT	mm	12:32:18	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	12:32:59	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	12:33:09	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	12:33:16	-0.005 OK	-0.002 OK	0.009
T1XX-FRT	mm	12:33:29	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:33:46	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	12:33:52	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	12:34:14	0.007 OK	-0.005 OK	0.017
T1XX-FRT	mm	12:34:21	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	12:35:19	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	12:35:29	-0.001 OK	0.003 OK	0.013
T1XX-FRT	mm	12:35:35	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	12:35:59	0.006 OK	-0.003 OK	0.018
T1XX-FRT	mm	12:36:06	0 OK	-0.004 OK	0.012
T1XX-FRT	mm	12:36:12	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	12:36:19	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	12:36:26	0.006 OK	-0.007 OK	0.017
T1XX-FRT	mm	12:36:51	0.007 OK	-0.007 OK	0.017
T1XX-FRT	mm	12:36:57	0 OK	-0.003 OK	0.012
T1XX-FRT	mm	12:37:21	0 OK	0.005 OK	0.018
T1XX-FRT	mm	12:37:27	-0.003 OK	0.001 OK	0.011
T1XX-FRT	mm	12:37:56	-0.003 OK	-0.002 OK	0.01

T1XX-FRT	mm	12:38:02	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	12:38:22	-0.007 OK	-0.002 OK	0.007
T1XX-FRT	mm	12:38:28	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	12:38:57	0.002 OK	-0.005 OK	0.014
T1XX-FRT	mm	12:39:04	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:39:23	-0.001 OK	0 OK	0.012
T1XX-FRT	mm	12:39:29	0 OK	-0.001 OK	0.013
T1XX-FRT	mm	12:39:56	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	12:40:07	0.004 OK	-0.002 OK	0.018
T1XX-FRT	mm	12:40:25	-0.003 OK	-0.004 OK	0.009
T1XX-FRT	mm	12:40:31	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	12:40:59	-0.003 OK	-0.001 OK	0.011
T1XX-FRT	mm	12:41:10	-0.004 OK	0.004 OK	0.011
T1XX-FRT	mm	12:41:28	0.008 OK	-0.006 OK	0.02
T1XX-FRT	mm	12:41:39	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	12:41:59	-0.002 OK	-0.004 OK	0.009
T1XX-FRT	mm	12:42:05	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:42:31	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	12:42:38	0.003 OK	-0.005 OK	0.015
T1XX-FRT	mm	12:43:03	-0.001 OK	-0.003 OK	0.01
T1XX-FRT	mm	12:43:14	0.005 OK	-0.005 OK	0.016
T1XX-FRT	mm	12:43:30	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	12:43:36	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	12:44:05	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	12:44:17	0.005 OK	-0.008 OK	0.016
T1XX-FRT	mm	12:44:34	-0.004 OK	-0.002 OK	0.008
T1XX-FRT	mm	12:44:40	-0.001 OK	-0.001 OK	0.013
T1XX-FRT	mm	12:45:15	-0.001 OK	-0.002 OK	0.011
T1XX-FRT	mm	12:45:21	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	12:45:40	-0.002 OK	0.006 OK	0.016
T1XX-FRT	mm	12:45:46	-0.003 OK	-0.002 OK	0.009
T1XX-FRT	mm	12:46:11	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	12:46:23	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	12:46:38	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:46:44	0.004 OK	0.002 OK	0.019
T1XX-FRT	mm	12:47:12	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	12:47:18	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:47:45	0.002 OK	0.006 OK	0.015
T1XX-FRT	mm	12:47:52	0.003 OK	0 OK	0.016
T1XX-FRT	mm	12:48:16	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	12:48:23	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:48:48	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	12:48:55	0 OK	-0.002 OK	0.013

T1XX-FRT	mm	12:49:23	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	12:49:29	-0.003 OK	-0.004 OK	0.008
T1XX-FRT	mm	12:49:48	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	12:49:59	-0.005 OK	-0.004 OK	0.007
T1XX-FRT	mm	12:50:28	0.003 OK	-0.004 OK	0.015
T1XX-FRT	mm	12:50:40	0.004 OK	0.004 OK	0.018
T1XX-FRT	mm	12:50:51	0 OK	-0.004 OK	0.012
T1XX-FRT	mm	12:51:02	0.006 OK	-0.005 OK	0.018
T1XX-FRT	mm	12:51:22	0 OK	-0.004 OK	0.014
T1XX-FRT	mm	12:51:33	-0.004 OK	0 OK	0.009
T1XX-FRT	mm	12:51:50	0.009 OK	-0.009 OK	0.018
T1XX-FRT	mm	12:51:57	-0.002 OK	-0.002 OK	0.01
T1XX-FRT	mm	12:52:25	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	12:52:31	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:52:56	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:53:05	-0.005 OK	-0.002 OK	0.008
T1XX-FRT	mm	12:53:12	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	12:53:38	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	12:55:45	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	12:55:51	0.001 OK	0.005 OK	0.019
T1XX-FRT	mm	12:56:10	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	12:56:40	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	12:56:47	-0.004 OK	-0.002 OK	0.009
T1XX-FRT	mm	12:56:54	-0.001 OK	-0.004 OK	0.011
T1XX-FRT	mm	12:57:08	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	12:57:19	0 OK	0 OK	0.013
T1XX-FRT	mm	12:57:33	0.002 OK	-0.007 OK	0.014
T1XX-FRT	mm	12:57:44	0.003 OK	-0.004 OK	0.014
T1XX-FRT	mm	12:57:58	0.006 OK	-0.006 OK	0.017
T1XX-FRT	mm	12:58:05	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	12:58:26	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	12:58:38	-0.001 OK	-0.004 OK	0.012
T1XX-FRT	mm	12:58:50	0.008 OK	-0.006 OK	0.021
T1XX-FRT	mm	12:59:01	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	12:59:15	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	12:59:21	-0.003 OK	-0.004 OK	0.01
T1XX-FRT	mm	12:59:38	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	12:59:49	0 OK	-0.003 OK	0.012
T1XX-FRT	mm	13:00:05	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	13:00:12	0.006 OK	-0.004 OK	0.018
T1XX-FRT	mm	13:00:28	0.003 OK	0.005 OK	0.017
T1XX-FRT	mm	13:00:35	0 OK	0.004 OK	0.015
T1XX-FRT	mm	13:01:53	0 OK	0.004 OK	0.015

T1XX-FRT	mm	13:02:02	-0.004 OK	-0.002 OK	0.009
T1XX-FRT	mm	13:02:08	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	13:02:42	0.002 OK	-0.004 OK	0.013
T1XX-FRT	mm	13:09:10	0.005 OK	-0.006 OK	0.015
T1XX-FRT	mm	13:10:03	-0.005 OK	-0.005 OK	0.006
T1XX-FRT	mm	13:10:10	-0.006 OK	-0.003 OK	0.007
T1XX-FRT	mm	13:10:32	-0.001 OK	-0.005 OK	0.011
T1XX-FRT	mm	13:10:38	-0.002 OK	0.003 OK	0.014
T1XX-FRT	mm	13:10:56	0.001 OK	-0.006 OK	0.012
T1XX-FRT	mm	13:11:03	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	13:11:25	-0.003 OK	-0.002 OK	0.009
T1XX-FRT	mm	13:11:31	-0.001 OK	0.005 OK	0.018
T1XX-FRT	mm	13:11:48	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	13:12:00	-0.001 OK	0.001 OK	0.014
T1XX-FRT	mm	13:12:13	0.012 NG	0.009 NG	0.024
T1XX-FRT	mm	13:12:19	-0.002 OK	-0.002 OK	0.01
T1XX-FRT	mm	13:12:57	-0.002 OK	-0.002 OK	0.01
T1XX-FRT	mm	13:13:07	-0.004 OK	0 OK	0.011
T1XX-FRT	mm	13:14:56	-0.004 OK	0 OK	0.011
T1XX-FRT	mm	13:15:02	0.006 OK	-0.005 OK	0.019
T1XX-FRT	mm	13:15:30	-0.015 NG	-0.005 OK	-0.003
T1XX-FRT	mm	13:16:13	-0.015 NG	-0.005 OK	-0.003
T1XX-FRT	mm	13:16:24	-0.011 NG	0 OK	0.003
T1XX-FRT	mm	13:16:31	-0.008 OK	-0.001 OK	0.006
T1XX-FRT	mm	13:16:44	-0.006 OK	-0.004 OK	0.006
T1XX-FRT	mm	13:16:55	0.003 OK	0.001 OK	0.013
T1XX-FRT	mm	13:17:01	-0.009 OK	-0.003 OK	0.003
T1XX-FRT	mm	13:17:08	-0.011 NG	-0.005 OK	0
T1XX-FRT	mm	13:17:14	-0.001 OK	-0.008 OK	0.009
T1XX-FRT	mm	13:17:21	-0.005 OK	-0.005 OK	0.006
T1XX-FRT	mm	13:17:28	-0.005 OK	-0.003 OK	0.006
T1XX-FRT	mm	13:17:34	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	13:17:40	0 OK	-0.003 OK	0.011
T1XX-FRT	mm	13:18:14	0 OK	-0.003 OK	0.011
T1XX-FRT	mm	13:18:21	-0.006 OK	-0.004 OK	0.005
T1XX-FRT	mm	13:18:27	-0.003 OK	-0.005 OK	0.009
T1XX-FRT	mm	13:18:41	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	13:18:47	-0.007 OK	0.002 OK	0.007
T1XX-FRT	mm	13:18:54	-0.001 OK	-0.004 OK	0.01
T1XX-FRT	mm	13:19:05	-0.008 OK	-0.003 OK	0.004
T1XX-FRT	mm	13:19:12	-0.003 OK	-0.002 OK	0.009
T1XX-FRT	mm	13:19:18	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	13:19:30	-0.001 OK	-0.004 OK	0.012

T1XX-FRT	mm	13:19:36	-0.003 OK	-0.003 OK	0.009
T1XX-FRT	mm	13:19:43	0 OK	-0.003 OK	0.012
T1XX-FRT	mm	13:19:50	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	13:19:56	-0.001 OK	-0.005 OK	0.01
T1XX-FRT	mm	13:20:22	-0.001 OK	-0.005 OK	0.01
T1XX-FRT	mm	13:20:29	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	13:20:35	-0.006 OK	0.004 OK	0.008
T1XX-FRT	mm	13:20:54	0 OK	-0.003 OK	0.012
T1XX-FRT	mm	13:21:05	-0.004 OK	-0.001 OK	0.009
T1XX-FRT	mm	13:21:17	-0.008 OK	-0.005 OK	0.002
T1XX-FRT	mm	13:21:23	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	13:21:47	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	13:21:58	0 OK	-0.004 OK	0.012
T1XX-FRT	mm	13:22:16	0.008 OK	-0.002 OK	0.018
T1XX-FRT	mm	13:22:22	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	13:22:44	0.004 OK	-0.004 OK	0.014
T1XX-FRT	mm	13:22:50	-0.004 OK	-0.003 OK	0.008
T1XX-FRT	mm	13:23:18	-0.003 OK	-0.003 OK	0.008
T1XX-FRT	mm	13:23:25	-0.005 OK	0.003 OK	0.009
T1XX-FRT	mm	13:23:50	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	13:23:57	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	13:24:25	-0.004 OK	-0.002 OK	0.008
T1XX-FRT	mm	13:24:32	-0.002 OK	-0.001 OK	0.011
T1XX-FRT	mm	13:24:49	-0.002 OK	-0.004 OK	0.011
T1XX-FRT	mm	13:24:55	-0.002 OK	0.003 OK	0.014
T1XX-FRT	mm	13:25:24	0.001 OK	0.002 OK	0.016
T1XX-FRT	mm	13:25:30	-0.007 OK	-0.004 OK	0.005
T1XX-FRT	mm	13:25:53	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	13:25:59	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	13:26:33	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	13:26:42	-0.001 OK	-0.004 OK	0.01
T1XX-FRT	mm	13:26:49	-0.007 OK	-0.002 OK	0.006
T1XX-FRT	mm	13:27:12	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	13:27:26	-0.004 OK	0.001 OK	0.011
T1XX-FRT	mm	13:27:32	-0.004 OK	-0.003 OK	0.008
T1XX-FRT	mm	13:28:01	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	13:28:12	0.002 OK	0.001 OK	0.015
T1XX-FRT	mm	13:28:33	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	13:29:05	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	13:29:11	-0.005 OK	0.006 OK	0.01
T1XX-FRT	mm	13:29:18	-0.006 OK	-0.004 OK	0.006
T1XX-FRT	mm	13:29:36	-0.007 OK	-0.002 OK	0.007
T1XX-FRT	mm	13:29:43	-0.003 OK	-0.003 OK	0.01

T1XX-FRT	mm	13:30:06	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	13:30:13	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	13:30:36	-0.004 OK	-0.002 OK	0.009
T1XX-FRT	mm	13:30:43	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	13:31:06	0.004 OK	-0.009 OK	0.013
T1XX-FRT	mm	13:31:12	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	13:31:43	-0.001 OK	-0.005 OK	0.009
T1XX-FRT	mm	13:31:54	-0.008 OK	-0.003 OK	0.005
T1XX-FRT	mm	13:32:06	0.004 OK	-0.009 OK	0.014
T1XX-FRT	mm	13:32:12	0.005 OK	-0.004 OK	0.017
T1XX-FRT	mm	13:32:42	-0.003 OK	-0.002 OK	0.009
T1XX-FRT	mm	13:32:49	0.003 OK	-0.001 OK	0.017
T1XX-FRT	mm	13:33:08	0.002 OK	-0.005 OK	0.013
T1XX-FRT	mm	13:33:19	-0.003 OK	-0.005 OK	0.008
T1XX-FRT	mm	13:33:41	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	13:33:53	-0.002 OK	0.004 OK	0.013
T1XX-FRT	mm	13:34:11	-0.005 OK	-0.004 OK	0.007
T1XX-FRT	mm	13:34:18	-0.002 OK	-0.004 OK	0.009
T1XX-FRT	mm	13:34:44	0.004 OK	-0.001 OK	0.018
T1XX-FRT	mm	13:34:51	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	13:35:14	0 OK	-0.004 OK	0.012
T1XX-FRT	mm	13:35:20	-0.002 OK	-0.001 OK	0.012
T1XX-FRT	mm	13:35:50	0.003 OK	-0.005 OK	0.014
T1XX-FRT	mm	13:35:56	0 OK	0 OK	0.014
T1XX-FRT	mm	13:36:17	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	13:37:38	0.006 OK	-0.007 OK	0.016
T1XX-FRT	mm	13:37:50	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	13:37:56	0.008 OK	-0.006 OK	0.018
T1XX-FRT	mm	13:38:03	-0.005 OK	0.003 OK	0.012
T1XX-FRT	mm	13:38:09	0 OK	-0.005 OK	0.013
T1XX-FRT	mm	13:38:16	-0.003 OK	-0.005 OK	0.008
T1XX-FRT	mm	13:38:23	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	13:38:29	-0.004 OK	-0.003 OK	0.007
T1XX-FRT	mm	13:38:35	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	13:39:49	0.004 OK	-0.006 OK	0.015
T1XX-FRT	mm	13:39:56	-0.006 OK	-0.005 OK	0.006
T1XX-FRT	mm	13:40:14	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	13:40:26	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	13:40:39	0.008 OK	-0.01 OK	0.016
T1XX-FRT	mm	13:40:45	0.01 OK	-0.008 OK	0.019
T1XX-FRT	mm	13:41:04	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	13:41:15	-0.005 OK	0 OK	0.009
T1XX-FRT	mm	13:41:28	-0.003 OK	-0.003 OK	0.009

T1XX-FRT	mm	13:41:39	0 OK	0.004 OK	0.018
T1XX-FRT	mm	13:41:54	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	13:42:22	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	13:42:29	-0.003 OK	-0.002 OK	0.009
T1XX-FRT	mm	13:42:35	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	13:42:48	-0.003 OK	0.002 OK	0.013
T1XX-FRT	mm	13:42:55	0.005 OK	-0.007 OK	0.015
T1XX-FRT	mm	13:43:07	0.002 OK	0.003 OK	0.014
T1XX-FRT	mm	13:43:19	-0.001 OK	0.004 OK	0.013
T1XX-FRT	mm	13:43:38	-0.003 OK	0.002 OK	0.011
T1XX-FRT	mm	13:43:49	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	13:44:05	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	13:44:11	-0.003 OK	0.001 OK	0.011
T1XX-FRT	mm	13:44:38	-0.006 OK	-0.004 OK	0.006
T1XX-FRT	mm	13:44:44	0 OK	-0.003 OK	0.012
T1XX-FRT	mm	13:45:09	-0.001 OK	-0.004 OK	0.01
T1XX-FRT	mm	13:45:16	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	13:45:38	-0.002 OK	0.005 OK	0.016
T1XX-FRT	mm	13:45:44	0 OK	-0.003 OK	0.012
T1XX-FRT	mm	13:46:12	-0.005 OK	-0.003 OK	0.008
T1XX-FRT	mm	13:46:23	0.002 OK	-0.003 OK	0.014
T1XX-FRT	mm	13:46:43	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	13:46:49	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	13:47:14	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	13:47:25	-0.002 OK	-0.004 OK	0.009
T1XX-FRT	mm	13:48:01	-0.002 OK	-0.004 OK	0.009
T1XX-FRT	mm	13:48:11	-0.005 OK	-0.002 OK	0.009
T1XX-FRT	mm	13:48:17	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	13:48:30	-0.002 OK	-0.002 OK	0.01
T1XX-FRT	mm	13:48:49	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	13:48:55	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	13:49:21	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	13:49:28	0.007 OK	-0.01 OK	0.016
T1XX-FRT	mm	13:49:52	-0.003 OK	0 OK	0.011
T1XX-FRT	mm	13:49:59	-0.004 OK	-0.003 OK	0.008
T1XX-FRT	mm	13:50:27	-0.005 OK	-0.002 OK	0.008
T1XX-FRT	mm	13:50:34	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	13:50:57	-0.003 OK	-0.003 OK	0.009
T1XX-FRT	mm	13:51:04	-0.001 OK	-0.004 OK	0.01
T1XX-FRT	mm	13:51:29	-0.003 OK	-0.001 OK	0.01
T1XX-FRT	mm	13:52:00	-0.003 OK	-0.001 OK	0.01
T1XX-FRT	mm	13:52:06	-0.005 OK	-0.005 OK	0.006
T1XX-FRT	mm	13:52:13	-0.001 OK	0.001 OK	0.014

T1XX-FRT	mm	13:52:33	-0.002 OK	-0.005 OK	0.01
T1XX-FRT	mm	13:52:40	-0.005 OK	0.005 OK	0.01
T1XX-FRT	mm	13:53:02	-0.004 OK	-0.003 OK	0.009
T1XX-FRT	mm	13:53:09	-0.002 OK	0.003 OK	0.015
T1XX-FRT	mm	13:53:39	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	13:53:50	0.002 OK	0.005 OK	0.015
T1XX-FRT	mm	13:54:02	-0.008 OK	0.004 OK	0.008
T1XX-FRT	mm	13:54:14	0.003 OK	-0.004 OK	0.014
T1XX-FRT	mm	13:55:15	0.003 OK	-0.004 OK	0.014
T1XX-FRT	mm	13:55:25	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	13:55:32	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	13:55:54	-0.003 OK	-0.003 OK	0.009
T1XX-FRT	mm	13:56:00	0.011 NG	-0.012 NG	0.019
T1XX-FRT	mm	13:56:07	0.004 OK	0.002 OK	0.019
T1XX-FRT	mm	13:56:14	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	13:56:47	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	13:56:53	0.004 OK	-0.004 OK	0.016
T1XX-FRT	mm	13:57:00	-0.004 OK	0.006 OK	0.011
T1XX-FRT	mm	13:57:15	-0.002 OK	-0.002 OK	0.01
T1XX-FRT	mm	13:57:21	0.001 OK	0.005 OK	0.019
T1XX-FRT	mm	13:57:49	0 OK	0 OK	0.014
T1XX-FRT	mm	13:57:55	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	13:58:21	0.003 OK	0.005 OK	0.016
T1XX-FRT	mm	13:58:28	-0.003 OK	-0.004 OK	0.009
T1XX-FRT	mm	13:58:50	-0.003 OK	-0.003 OK	0.009
T1XX-FRT	mm	13:59:01	-0.001 OK	-0.002 OK	0.011
T1XX-FRT	mm	13:59:21	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	13:59:32	0.002 OK	-0.002 OK	0.014
T1XX-FRT	mm	13:59:53	0.002 OK	-0.001 OK	0.015
T1XX-FRT	mm	14:00:00	-0.002 OK	-0.002 OK	0.01
T1XX-FRT	mm	14:00:24	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	14:00:36	0 OK	0.002 OK	0.016
T1XX-FRT	mm	14:06:11	0 OK	0.002 OK	0.016
T1XX-FRT	mm	14:06:21	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	14:06:27	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	14:06:40	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	14:09:35	0.001 OK	-0.009 OK	0.01
T1XX-FRT	mm	14:09:41	0.003 OK	-0.007 OK	0.014
T1XX-FRT	mm	14:10:14	0.003 OK	-0.005 OK	0.015
T1XX-FRT	mm	14:10:24	0.004 OK	-0.005 OK	0.015
T1XX-FRT	mm	14:10:47	0.004 OK	-0.004 OK	0.016
T1XX-FRT	mm	14:10:54	-0.003 OK	0 OK	0.01
T1XX-FRT	mm	14:11:20	-0.001 OK	0.006 OK	0.013

T1XX-FRT	mm	14:11:27	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	14:11:49	0.003 OK	-0.006 OK	0.015
T1XX-FRT	mm	14:12:00	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	14:12:20	0.001 OK	-0.001 OK	0.016
T1XX-FRT	mm	14:12:26	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	14:12:54	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	14:13:01	0.006 OK	0.001 OK	0.021
T1XX-FRT	mm	14:13:24	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	14:13:30	-0.001 OK	-0.001 OK	0.012
T1XX-FRT	mm	14:14:01	0.004 OK	-0.001 OK	0.018
T1XX-FRT	mm	14:14:08	-0.001 OK	-0.002 OK	0.011
T1XX-FRT	mm	14:14:29	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	14:14:40	0 OK	0.005 OK	0.018
T1XX-FRT	mm	14:14:57	-0.001 OK	-0.004 OK	0.012
T1XX-FRT	mm	14:15:04	-0.001 OK	0.005 OK	0.014
T1XX-FRT	mm	14:15:28	0.005 OK	-0.002 OK	0.018
T1XX-FRT	mm	14:15:35	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	14:15:59	0.009 OK	-0.006 OK	0.018
T1XX-FRT	mm	14:16:06	0 OK	0.003 OK	0.014
T1XX-FRT	mm	14:16:26	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	14:16:33	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	14:17:01	-0.001 OK	-0.005 OK	0.01
T1XX-FRT	mm	14:17:08	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	14:17:29	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	14:17:36	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	14:17:59	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	14:18:32	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	14:18:39	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	14:18:45	0.005 OK	-0.003 OK	0.018
T1XX-FRT	mm	14:19:29	0.005 OK	-0.003 OK	0.018
T1XX-FRT	mm	14:19:42	0.008 OK	-0.002 OK	0.021
T1XX-FRT	mm	14:19:55	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	14:20:02	0.004 OK	0.002 OK	0.017
T1XX-FRT	mm	14:20:13	0.003 OK	-0.004 OK	0.014
T1XX-FRT	mm	14:20:20	0.003 OK	0 OK	0.017
T1XX-FRT	mm	14:20:32	-0.003 OK	-0.003 OK	0.009
T1XX-FRT	mm	14:20:43	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	14:21:06	0.01 OK	-0.007 OK	0.019
T1XX-FRT	mm	14:21:12	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	14:21:33	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	14:21:39	0.003 OK	-0.005 OK	0.016
T1XX-FRT	mm	14:22:06	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	14:22:17	-0.002 OK	0.004 OK	0.013

T1XX-FRT	mm	14:22:33	0.005 OK	0.006 OK	0.02
T1XX-FRT	mm	14:22:39	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	14:23:09	0.007 OK	-0.01 OK	0.016
T1XX-FRT	mm	14:23:19	0.002 OK	-0.001 OK	0.017
T1XX-FRT	mm	14:23:35	0.001 OK	0.004 OK	0.016
T1XX-FRT	mm	14:23:42	0.006 OK	0.002 OK	0.023
T1XX-FRT	mm	14:24:25	0.006 OK	0.002 OK	0.023
T1XX-FRT	mm	14:24:34	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	14:24:41	0.007 OK	-0.01 OK	0.017
T1XX-FRT	mm	14:24:53	0.004 OK	-0.004 OK	0.016
T1XX-FRT	mm	14:26:07	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	14:26:14	0.006 OK	-0.003 OK	0.02
T1XX-FRT	mm	14:26:32	-0.001 OK	-0.001 OK	0.012
T1XX-FRT	mm	14:26:39	0 OK	0.004 OK	0.014
T1XX-FRT	mm	14:26:57	-0.003 OK	0.006 OK	0.013
T1XX-FRT	mm	14:27:09	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	14:27:23	0.004 OK	-0.006 OK	0.015
T1XX-FRT	mm	14:27:34	0.007 OK	-0.004 OK	0.019
T1XX-FRT	mm	14:27:47	0.001 OK	0.002 OK	0.016
T1XX-FRT	mm	14:27:59	0.003 OK	0.008 OK	0.019
T1XX-FRT	mm	14:28:35	0.003 OK	0.008 OK	0.019
T1XX-FRT	mm	14:28:48	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	14:28:54	0.003 OK	-0.004 OK	0.017
T1XX-FRT	mm	14:29:08	0.001 OK	-0.001 OK	0.015
T1XX-FRT	mm	14:29:14	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	14:29:25	0.002 OK	-0.007 OK	0.013
T1XX-FRT	mm	14:29:36	0.002 OK	-0.001 OK	0.016
T1XX-FRT	mm	14:29:48	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	14:30:00	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	14:30:07	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	14:30:26	-0.004 OK	-0.003 OK	0.01
T1XX-FRT	mm	14:30:38	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	14:30:53	-0.002 OK	0.005 OK	0.014
T1XX-FRT	mm	14:31:00	0.001 OK	0 OK	0.015
T1XX-FRT	mm	14:31:27	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	14:31:34	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	14:31:56	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	14:32:07	0 OK	-0.001 OK	0.014
T1XX-FRT	mm	14:32:29	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	14:32:41	0.005 OK	-0.003 OK	0.018
T1XX-FRT	mm	14:33:02	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	14:33:08	0.006 OK	-0.004 OK	0.02
T1XX-FRT	mm	14:33:37	0 OK	-0.002 OK	0.014

T1XX-FRT	mm	14:33:44	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	14:34:03	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	14:34:09	-0.002 OK	0.004 OK	0.012
T1XX-FRT	mm	14:35:38	-0.002 OK	0.004 OK	0.012
T1XX-FRT	mm	14:35:49	0.01 OK	-0.005 OK	0.022
T1XX-FRT	mm	14:35:56	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	14:36:14	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	14:36:20	0.008 OK	0.002 OK	0.02
T1XX-FRT	mm	14:36:31	0.009 OK	-0.004 OK	0.022
T1XX-FRT	mm	14:36:38	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	14:36:50	0.006 OK	-0.003 OK	0.02
T1XX-FRT	mm	14:36:56	0.004 OK	0.006 OK	0.019
T1XX-FRT	mm	14:37:03	0.001 OK	0.005 OK	0.017
T1XX-FRT	mm	14:37:41	0.003 OK	-0.005 OK	0.015
T1XX-FRT	mm	14:37:48	0.001 OK	-0.006 OK	0.013
T1XX-FRT	mm	14:38:29	0.003 OK	-0.003 OK	0.017
T1XX-FRT	mm	14:38:36	0.007 OK	-0.005 OK	0.019
T1XX-FRT	mm	14:39:11	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	14:39:22	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	14:39:47	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	14:39:58	0.002 OK	0.001 OK	0.017
T1XX-FRT	mm	14:40:15	0.019 NG	-0.003 OK	0.033
T1XX-FRT	mm	14:40:48	0.019 NG	-0.003 OK	0.033
T1XX-FRT	mm	14:40:55	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	14:41:02	0.003 OK	-0.006 OK	0.016
T1XX-FRT	mm	14:41:24	-0.004 OK	0.006 OK	0.013
T1XX-FRT	mm	14:41:53	-0.004 OK	0.006 OK	0.013
T1XX-FRT	mm	14:42:00	0 OK	0.005 OK	0.016
T1XX-FRT	mm	14:42:06	0.005 OK	-0.005 OK	0.018
T1XX-FRT	mm	14:42:22	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	14:42:28	0 OK	0.002 OK	0.016
T1XX-FRT	mm	14:42:53	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	14:43:04	0.007 OK	-0.007 OK	0.019
T1XX-FRT	mm	14:43:23	0.008 OK	-0.006 OK	0.02
T1XX-FRT	mm	14:43:35	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	14:43:58	0.006 OK	-0.007 OK	0.018
T1XX-FRT	mm	14:44:05	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	14:44:41	0.004 OK	-0.007 OK	0.017
T1XX-FRT	mm	14:44:48	0.002 OK	0.002 OK	0.018
T1XX-FRT	mm	14:45:14	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	14:45:21	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	14:45:51	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	14:46:02	0.005 OK	0.002 OK	0.021

T1XX-FRT	mm	14:46:20	-0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	14:46:26	0.005 OK	-0.002 OK	0.019
T1XX-FRT	mm	14:46:48	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	14:46:55	0.008 OK	-0.007 OK	0.019
T1XX-FRT	mm	14:47:18	0.003 OK	0.002 OK	0.019
T1XX-FRT	mm	14:47:30	0.002 OK	0.003 OK	0.016
T1XX-FRT	mm	14:47:46	-0.004 OK	0.003 OK	0.012
T1XX-FRT	mm	14:48:27	-0.004 OK	0.003 OK	0.012
T1XX-FRT	mm	14:48:33	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	14:48:40	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	14:48:58	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	14:49:09	0 OK	0.007 OK	0.016
T1XX-FRT	mm	14:49:20	-0.001 OK	-0.004 OK	0.012
T1XX-FRT	mm	14:49:32	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	14:49:46	0.008 OK	0.001 OK	0.02
T1XX-FRT	mm	14:49:53	0.004 OK	-0.004 OK	0.017
T1XX-FRT	mm	14:50:16	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	14:50:27	0.009 OK	-0.006 OK	0.022
T1XX-FRT	mm	14:50:48	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	14:50:54	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	14:51:18	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	14:51:25	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	14:51:51	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	14:51:57	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	14:52:16	-0.003 OK	0.006 OK	0.012
T1XX-FRT	mm	14:52:23	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	14:52:51	0.006 OK	-0.003 OK	0.02
T1XX-FRT	mm	14:53:02	0.004 OK	0 OK	0.019
T1XX-FRT	mm	14:53:18	0.002 OK	-0.004 OK	0.016
T1XX-FRT	mm	14:53:24	0.004 OK	-0.002 OK	0.018
T1XX-FRT	mm	14:53:49	0.005 OK	-0.006 OK	0.018
T1XX-FRT	mm	14:54:00	0.005 OK	-0.006 OK	0.017
T1XX-FRT	mm	14:54:16	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	14:54:29	0.006 OK	-0.008 OK	0.017
T1XX-FRT	mm	14:54:48	0.003 OK	-0.003 OK	0.019
T1XX-FRT	mm	14:54:55	0.006 OK	-0.003 OK	0.02
T1XX-FRT	mm	14:55:16	0.003 OK	-0.003 OK	0.017
T1XX-FRT	mm	14:55:27	0.009 OK	-0.006 OK	0.022
T1XX-FRT	mm	14:55:50	0.009 OK	-0.007 OK	0.02
T1XX-FRT	mm	14:56:02	0.012 NG	-0.01 OK	0.021
T1XX-FRT	mm	14:56:20	0.007 OK	-0.005 OK	0.019
T1XX-FRT	mm	14:56:32	0.002 OK	0.002 OK	0.018
T1XX-FRT	mm	14:56:58	0.005 OK	-0.008 OK	0.016

T1XX-FRT	mm	14:57:25	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	14:57:56	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	14:58:02	0.008 OK	-0.001 OK	0.022
T1XX-FRT	mm	14:58:09	0.002 OK	-0.001 OK	0.017
T1XX-FRT	mm	14:58:26	0.003 OK	-0.003 OK	0.017
T1XX-FRT	mm	14:58:33	0.005 OK	-0.004 OK	0.018
T1XX-FRT	mm	14:58:40	0.002 OK	-0.001 OK	0.016
T1XX-FRT	mm	14:58:59	0.004 OK	0.001 OK	0.02
T1XX-FRT	mm	14:59:10	0.004 OK	0 OK	0.019
T1XX-FRT	mm	14:59:28	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	14:59:34	0.01 OK	0.002 OK	0.023
T1XX-FRT	mm	14:59:57	0.004 OK	-0.003 OK	0.018
T1XX-FRT	mm	15:00:08	0.004 OK	-0.001 OK	0.019
T1XX-FRT	mm	15:00:27	0.002 OK	0 OK	0.016
T1XX-FRT	mm	15:00:34	0 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:00:59	-0.001 OK	-0.004 OK	0.012
T1XX-FRT	mm	15:01:10	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	15:01:32	0.002 OK	-0.003 OK	0.017
T1XX-FRT	mm	15:01:38	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	15:02:01	0.003 OK	-0.003 OK	0.017
T1XX-FRT	mm	15:02:08	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:02:35	0 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:02:42	0.001 OK	-0.004 OK	0.015
T1XX-FRT	mm	15:03:00	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	15:03:12	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:03:32	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	15:03:43	0.005 OK	-0.004 OK	0.019
T1XX-FRT	mm	15:04:03	-0.001 OK	0.002 OK	0.014
T1XX-FRT	mm	15:04:10	0.007 OK	-0.004 OK	0.02
T1XX-FRT	mm	15:06:09	0.007 OK	-0.004 OK	0.02
T1XX-FRT	mm	15:06:17	0.007 OK	-0.005 OK	0.02
T1XX-FRT	mm	15:06:24	0.01 OK	-0.004 OK	0.024
T1XX-FRT	mm	15:07:07	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	15:08:12	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	15:08:23	0.006 OK	-0.005 OK	0.019
T1XX-FRT	mm	15:08:30	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:08:43	0.005 OK	-0.005 OK	0.017
T1XX-FRT	mm	15:09:21	0.005 OK	-0.005 OK	0.017
T1XX-FRT	mm	15:09:28	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	15:09:34	0.004 OK	-0.006 OK	0.016
T1XX-FRT	mm	15:09:52	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	15:09:59	0.004 OK	-0.003 OK	0.018
T1XX-FRT	mm	15:10:06	0.002 OK	-0.003 OK	0.016

T1XX-FRT	mm	15:10:16	0.008 OK	-0.002 OK	0.023
T1XX-FRT	mm	15:10:23	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	15:10:30	0.005 OK	-0.001 OK	0.018
T1XX-FRT	mm	15:10:41	0.006 OK	-0.001 OK	0.02
T1XX-FRT	mm	15:10:53	0.008 OK	-0.006 OK	0.019
T1XX-FRT	mm	15:10:59	0.006 OK	0.008 OK	0.019
T1XX-FRT	mm	15:11:11	-0.001 OK	0.003 OK	0.014
T1XX-FRT	mm	15:11:18	0.003 OK	-0.002 OK	0.018
T1XX-FRT	mm	15:11:30	0.004 OK	0.004 OK	0.022
T1XX-FRT	mm	15:11:36	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	15:11:43	0.002 OK	-0.001 OK	0.017
T1XX-FRT	mm	15:11:54	0.006 OK	-0.004 OK	0.02
T1XX-FRT	mm	15:12:05	0.007 OK	-0.003 OK	0.02
T1XX-FRT	mm	15:12:12	0.006 OK	-0.001 OK	0.019
T1XX-FRT	mm	15:12:24	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:12:36	0.003 OK	0.001 OK	0.018
T1XX-FRT	mm	15:12:50	0.003 OK	-0.001 OK	0.017
T1XX-FRT	mm	15:12:56	0.003 OK	-0.004 OK	0.018
T1XX-FRT	mm	15:13:15	0.007 OK	-0.003 OK	0.021
T1XX-FRT	mm	15:13:26	0.006 OK	-0.003 OK	0.02
T1XX-FRT	mm	15:13:40	0.002 OK	-0.004 OK	0.016
T1XX-FRT	mm	15:13:51	-0.005 OK	-0.004 OK	0.008
T1XX-FRT	mm	15:14:04	-0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	15:14:15	0.002 OK	-0.001 OK	0.016
T1XX-FRT	mm	15:14:30	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	15:17:06	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	15:17:13	0.006 OK	-0.005 OK	0.019
T1XX-FRT	mm	15:17:20	0.005 OK	-0.002 OK	0.019
T1XX-FRT	mm	15:17:32	-0.001 OK	-0.001 OK	0.014
T1XX-FRT	mm	15:17:39	0.001 OK	0.004 OK	0.015
T1XX-FRT	mm	15:17:46	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	15:17:52	-0.003 OK	0 OK	0.012
T1XX-FRT	mm	15:17:58	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	15:18:05	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:18:12	0.005 OK	-0.009 OK	0.016
T1XX-FRT	mm	15:18:18	0 OK	-0.001 OK	0.015
T1XX-FRT	mm	15:18:25	0.003 OK	-0.005 OK	0.015
T1XX-FRT	mm	15:18:32	0.001 OK	0.006 OK	0.02
T1XX-FRT	mm	15:18:38	0.004 OK	-0.005 OK	0.017
T1XX-FRT	mm	15:18:45	0.001 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:18:51	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	15:18:58	0.004 OK	-0.005 OK	0.017
T1XX-FRT	mm	15:19:11	0.001 OK	-0.001 OK	0.015

T1XX-FRT	mm	15:19:17	0.003 OK	0.002 OK	0.019
T1XX-FRT	mm	15:19:36	0 OK	-0.004 OK	0.014
T1XX-FRT	mm	15:19:43	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:20:01	0.005 OK	-0.002 OK	0.019
T1XX-FRT	mm	15:20:12	0.004 OK	-0.002 OK	0.018
T1XX-FRT	mm	15:20:26	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	15:20:38	0.002 OK	0.006 OK	0.017
T1XX-FRT	mm	15:20:51	0.004 OK	-0.002 OK	0.018
T1XX-FRT	mm	15:20:58	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	15:21:17	-0.003 OK	-0.002 OK	0.012
T1XX-FRT	mm	15:21:23	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	15:21:42	0.003 OK	-0.005 OK	0.017
T1XX-FRT	mm	15:21:48	0 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:22:10	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:22:17	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	15:22:35	0.001 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:22:42	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:23:03	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	15:23:10	0.003 OK	-0.001 OK	0.017
T1XX-FRT	mm	15:23:32	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	15:23:43	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	15:24:05	0.003 OK	-0.002 OK	0.018
T1XX-FRT	mm	15:24:11	0.006 OK	-0.006 OK	0.018
T1XX-FRT	mm	15:24:37	0.006 OK	-0.003 OK	0.02
T1XX-FRT	mm	15:24:48	0.006 OK	-0.003 OK	0.02
T1XX-FRT	mm	15:25:12	0.006 OK	-0.004 OK	0.019
T1XX-FRT	mm	15:25:40	0.006 OK	-0.004 OK	0.019
T1XX-FRT	mm	15:25:46	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	15:25:53	0.001 OK	-0.005 OK	0.014
T1XX-FRT	mm	15:26:06	0.003 OK	-0.001 OK	0.018
T1XX-FRT	mm	15:26:13	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:26:53	0.006 OK	-0.005 OK	0.018
T1XX-FRT	mm	15:27:04	0.003 OK	-0.004 OK	0.016
T1XX-FRT	mm	15:27:39	0.009 OK	-0.005 OK	0.022
T1XX-FRT	mm	15:27:50	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	15:28:11	0.003 OK	-0.003 OK	0.017
T1XX-FRT	mm	15:28:23	0.004 OK	0.003 OK	0.019
T1XX-FRT	mm	15:28:49	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:29:22	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:29:29	0.005 OK	-0.003 OK	0.019
T1XX-FRT	mm	15:29:35	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	15:29:58	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	15:30:05	0.004 OK	-0.003 OK	0.018

T1XX-FRT	mm	15:30:20	-0.002 OK	-0.004 OK	0.012
T1XX-FRT	mm	15:30:27	0.009 OK	-0.007 OK	0.02
T1XX-FRT	mm	15:30:54	0.002 OK	-0.002 OK	0.017
T1XX-FRT	mm	15:31:05	0 OK	-0.001 OK	0.015
T1XX-FRT	mm	15:31:23	0.006 OK	-0.009 OK	0.017
T1XX-FRT	mm	15:31:30	0 OK	0.001 OK	0.014
T1XX-FRT	mm	15:31:53	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	15:31:59	0.003 OK	-0.003 OK	0.017
T1XX-FRT	mm	15:32:22	0 OK	-0.003 OK	0.015
T1XX-FRT	mm	15:32:33	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	15:32:53	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	15:32:59	0.004 OK	0.005 OK	0.018
T1XX-FRT	mm	15:33:24	0.006 OK	-0.004 OK	0.019
T1XX-FRT	mm	15:33:31	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:33:58	0.006 OK	0.007 OK	0.02
T1XX-FRT	mm	15:34:04	0 OK	0.001 OK	0.015
T1XX-FRT	mm	15:34:31	0.006 OK	-0.003 OK	0.02
T1XX-FRT	mm	15:34:42	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	15:35:04	0.004 OK	-0.002 OK	0.019
T1XX-FRT	mm	15:35:10	0.001 OK	0 OK	0.016
T1XX-FRT	mm	15:35:36	0.003 OK	-0.005 OK	0.016
T1XX-FRT	mm	15:35:43	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	15:36:04	-0.004 OK	-0.001 OK	0.01
T1XX-FRT	mm	15:36:10	0.007 OK	-0.007 OK	0.018
T1XX-FRT	mm	15:36:40	0.005 OK	-0.002 OK	0.019
T1XX-FRT	mm	15:36:51	0.003 OK	-0.002 OK	0.017
T1XX-FRT	mm	15:37:04	0.005 OK	-0.005 OK	0.017
T1XX-FRT	mm	15:37:11	0.007 OK	-0.003 OK	0.02
T1XX-FRT	mm	15:37:30	0.003 OK	-0.002 OK	0.017
T1XX-FRT	mm	15:37:37	0 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:38:01	0 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:38:11	-0.003 OK	-0.004 OK	0.011
T1XX-FRT	mm	15:38:17	0.005 OK	-0.003 OK	0.02
T1XX-FRT	mm	15:38:40	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	15:38:59	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	15:39:06	-0.003 OK	-0.002 OK	0.013
T1XX-FRT	mm	15:39:38	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	15:39:49	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	15:40:04	0.005 OK	-0.006 OK	0.017
T1XX-FRT	mm	15:40:10	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	15:40:36	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	15:40:43	0.008 OK	-0.008 OK	0.02
T1XX-FRT	mm	15:41:12	0 OK	-0.004 OK	0.013

T1XX-FRT	mm	15:41:23	0.009 OK	-0.01 OK	0.02
T1XX-FRT	mm	15:41:39	0.006 OK	-0.005 OK	0.018
T1XX-FRT	mm	15:41:50	0.004 OK	-0.005 OK	0.018
T1XX-FRT	mm	15:42:05	0.006 OK	0.001 OK	0.019
T1XX-FRT	mm	15:42:11	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	15:43:27	0.002 OK	-0.005 OK	0.014
T1XX-FRT	mm	15:43:33	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:43:56	0.01 OK	-0.005 OK	0.021
T1XX-FRT	mm	15:44:03	0.005 OK	-0.004 OK	0.019
T1XX-FRT	mm	15:44:21	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	15:44:27	0.003 OK	-0.004 OK	0.016
T1XX-FRT	mm	15:44:45	0.005 OK	-0.007 OK	0.017
T1XX-FRT	mm	15:44:57	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:45:11	0 OK	-0.005 OK	0.012
T1XX-FRT	mm	15:45:18	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	15:45:36	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	15:45:42	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	15:46:02	0.007 OK	0.001 OK	0.02
T1XX-FRT	mm	15:46:08	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	15:46:27	0.001 OK	-0.004 OK	0.015
T1XX-FRT	mm	15:46:33	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	15:46:51	0.01 OK	-0.01 OK	0.02
T1XX-FRT	mm	15:46:58	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	15:47:17	0.007 OK	-0.004 OK	0.02
T1XX-FRT	mm	15:47:29	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:47:42	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:47:54	0.001 OK	0 OK	0.016
T1XX-FRT	mm	15:48:07	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	15:48:14	0.001 OK	0.007 OK	0.018
T1XX-FRT	mm	15:48:32	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	15:48:39	-0.001 OK	-0.001 OK	0.014
T1XX-FRT	mm	15:49:02	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	15:49:09	-0.001 OK	0.004 OK	0.017
T1XX-FRT	mm	15:49:35	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	15:49:41	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	15:50:01	0 OK	0 OK	0.015
T1XX-FRT	mm	15:50:08	0.006 OK	-0.005 OK	0.019
T1XX-FRT	mm	15:50:26	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	15:50:37	0.001 OK	0.003 OK	0.016
T1XX-FRT	mm	15:54:06	0.001 OK	0.003 OK	0.016
T1XX-FRT	mm	15:54:18	0.002 OK	-0.003 OK	0.017
T1XX-FRT	mm	15:54:24	0.002 OK	-0.003 OK	0.017
T1XX-FRT	mm	15:54:42	0 OK	-0.003 OK	0.013

T1XX-FRT	mm	15:54:54	-0.006 OK	-0.003 OK	0.007
T1XX-FRT	mm	15:55:05	0.007 OK	-0.01 OK	0.017
T1XX-FRT	mm	15:55:11	0.009 OK	-0.004 OK	0.023
T1XX-FRT	mm	15:55:18	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	15:55:25	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	15:55:31	-0.003 OK	0.002 OK	0.012
T1XX-FRT	mm	15:55:38	0 OK	-0.005 OK	0.012
T1XX-FRT	mm	15:55:50	0.002 OK	-0.002 OK	0.017
T1XX-FRT	mm	15:55:56	-0.001 OK	-0.004 OK	0.012
T1XX-FRT	mm	15:56:03	-0.003 OK	0.007 OK	0.018
T1XX-FRT	mm	15:56:09	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	15:56:16	0 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:56:27	0 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:56:39	0.009 OK	-0.004 OK	0.019
T1XX-FRT	mm	15:56:45	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	15:56:52	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	15:57:03	0.008 OK	-0.008 OK	0.019
T1XX-FRT	mm	15:57:14	-0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	15:57:21	-0.001 OK	-0.001 OK	0.013
T1XX-FRT	mm	15:57:28	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	15:57:34	0.003 OK	-0.005 OK	0.016
T1XX-FRT	mm	15:57:41	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	15:57:54	0.001 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:58:05	-0.003 OK	-0.002 OK	0.013
T1XX-FRT	mm	15:58:19	0.004 OK	-0.005 OK	0.017
T1XX-FRT	mm	15:58:25	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	15:58:43	0.002 OK	-0.004 OK	0.016
T1XX-FRT	mm	15:58:55	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	15:59:09	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	15:59:55	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	16:00:01	0.002 OK	-0.005 OK	0.015
T1XX-FRT	mm	16:00:08	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	16:00:25	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	16:00:32	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	16:00:44	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	16:00:51	0.003 OK	-0.002 OK	0.018
T1XX-FRT	mm	16:01:02	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	16:01:13	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	16:01:25	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	16:01:32	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	16:01:41	0.001 OK	0 OK	0.016
T1XX-FRT	mm	16:02:12	0.001 OK	0 OK	0.016
T1XX-FRT	mm	16:02:19	-0.001 OK	-0.002 OK	0.013

T1XX-FRT	mm	16:02:25	0.003 OK	0.007 OK	0.019
T1XX-FRT	mm	16:03:20	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	16:03:27	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	16:03:40	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	16:03:47	-0.004 OK	-0.003 OK	0.01
T1XX-FRT	mm	16:03:53	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:04:00	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	16:04:11	0.004 OK	-0.003 OK	0.018
T1XX-FRT	mm	16:04:37	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	16:05:33	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	16:05:40	0.01 OK	-0.008 OK	0.021
T1XX-FRT	mm	16:05:47	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	16:06:00	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	16:06:11	0.004 OK	-0.001 OK	0.019
T1XX-FRT	mm	16:06:22	-0.001 OK	0.002 OK	0.015
T1XX-FRT	mm	16:06:29	0.01 OK	-0.01 OK	0.02
T1XX-FRT	mm	16:06:35	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	16:06:42	-0.004 OK	0.007 OK	0.013
T1XX-FRT	mm	16:06:53	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	16:07:00	0.003 OK	0 OK	0.018
T1XX-FRT	mm	16:07:19	0.002 OK	0.006 OK	0.021
T1XX-FRT	mm	16:07:25	0.003 OK	-0.002 OK	0.017
T1XX-FRT	mm	16:07:52	0.004 OK	0.004 OK	0.018
T1XX-FRT	mm	16:07:59	0.004 OK	-0.001 OK	0.019
T1XX-FRT	mm	16:08:21	0.005 OK	0 OK	0.02
T1XX-FRT	mm	16:08:33	0.004 OK	-0.001 OK	0.018
T1XX-FRT	mm	16:08:55	0.01 OK	-0.009 OK	0.02
T1XX-FRT	mm	16:09:07	0.004 OK	0.004 OK	0.019
T1XX-FRT	mm	16:09:21	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	16:09:32	0.003 OK	-0.002 OK	0.018
T1XX-FRT	mm	16:09:46	-0.003 OK	-0.004 OK	0.009
T1XX-FRT	mm	16:09:52	0.006 OK	-0.005 OK	0.018
T1XX-FRT	mm	16:10:15	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	16:10:21	0 OK	-0.001 OK	0.014
T1XX-FRT	mm	16:10:47	0.002 OK	0.004 OK	0.019
T1XX-FRT	mm	16:10:58	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	16:11:16	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	16:11:22	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:11:50	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	16:11:57	0.005 OK	-0.003 OK	0.018
T1XX-FRT	mm	16:12:19	0.002 OK	-0.001 OK	0.016
T1XX-FRT	mm	16:12:30	0.001 OK	-0.001 OK	0.015
T1XX-FRT	mm	16:12:45	0.002 OK	-0.003 OK	0.016

T1XX-FRT	mm	16:12:57	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	16:13:11	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	16:13:22	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	16:13:39	0.003 OK	0.003 OK	0.02
T1XX-FRT	mm	16:13:46	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	16:14:14	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:14:26	0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:14:40	-0.001 OK	0.004 OK	0.014
T1XX-FRT	mm	16:14:52	0.001 OK	-0.001 OK	0.015
T1XX-FRT	mm	16:15:07	0.005 OK	-0.004 OK	0.017
T1XX-FRT	mm	16:15:13	0.004 OK	-0.005 OK	0.015
T1XX-FRT	mm	16:15:35	0.004 OK	0.006 OK	0.016
T1XX-FRT	mm	16:16:07	0.004 OK	0.006 OK	0.016
T1XX-FRT	mm	16:16:14	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:16:20	0 OK	-0.001 OK	0.013
T1XX-FRT	mm	16:16:37	0.002 OK	-0.001 OK	0.015
T1XX-FRT	mm	16:16:44	0 OK	-0.005 OK	0.012
T1XX-FRT	mm	16:17:02	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	16:17:13	0.001 OK	-0.001 OK	0.014
T1XX-FRT	mm	16:17:28	0.009 OK	-0.007 OK	0.019
T1XX-FRT	mm	16:17:40	0.002 OK	-0.001 OK	0.015
T1XX-FRT	mm	16:17:54	0 OK	-0.004 OK	0.011
T1XX-FRT	mm	16:18:01	0.005 OK	-0.004 OK	0.018
T1XX-FRT	mm	16:18:28	0.009 OK	0.005 OK	0.023
T1XX-FRT	mm	16:18:35	0.005 OK	-0.003 OK	0.019
T1XX-FRT	mm	16:19:43	0.002 OK	-0.003 OK	0.014
T1XX-FRT	mm	16:19:54	0.001 OK	-0.001 OK	0.015
T1XX-FRT	mm	16:20:08	0.004 OK	-0.002 OK	0.018
T1XX-FRT	mm	16:20:19	0.002 OK	-0.001 OK	0.015
T1XX-FRT	mm	16:20:33	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:20:44	-0.001 OK	0 OK	0.014
T1XX-FRT	mm	16:20:58	-0.003 OK	0.005 OK	0.012
T1XX-FRT	mm	16:21:10	-0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:21:23	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	16:21:34	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	16:21:48	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	16:21:59	0.003 OK	0.006 OK	0.019
T1XX-FRT	mm	16:22:12	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	16:22:24	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	16:22:38	0.004 OK	-0.005 OK	0.016
T1XX-FRT	mm	16:22:49	0.003 OK	-0.005 OK	0.015
T1XX-FRT	mm	16:23:02	0 OK	0.002 OK	0.015
T1XX-FRT	mm	16:23:13	-0.004 OK	-0.002 OK	0.011

T1XX-FRT	mm	16:23:32	0.01 OK	-0.01 OK	0.019
T1XX-FRT	mm	16:23:39	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	16:23:57	0.005 OK	-0.002 OK	0.016
T1XX-FRT	mm	16:24:08	-0.002 OK	-0.004 OK	0.011
T1XX-FRT	mm	16:24:21	0.011 NG	-0.005 OK	0.02
T1XX-FRT	mm	16:24:32	0.001 OK	0.005 OK	0.016
T1XX-FRT	mm	16:24:59	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	16:25:10	0.005 OK	-0.002 OK	0.018
T1XX-FRT	mm	16:25:27	-0.003 OK	-0.004 OK	0.009
T1XX-FRT	mm	16:25:38	0.01 OK	-0.01 OK	0.019
T1XX-FRT	mm	16:25:52	0.01 OK	-0.008 OK	0.02
T1XX-FRT	mm	16:26:03	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	16:26:20	0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:26:32	0.012 NG	-0.008 OK	0.021
T1XX-FRT	mm	16:36:42	-0.001 OK	-0.005 OK	0.01
T1XX-FRT	mm	16:36:54	0.004 OK	-0.004 OK	0.015
T1XX-FRT	mm	16:37:29	0 OK	-0.005 OK	0.011
T1XX-FRT	mm	16:37:40	0.002 OK	0.003 OK	0.019
T1XX-FRT	mm	16:37:55	-0.001 OK	-0.001 OK	0.013
T1XX-FRT	mm	16:38:28	0.003 OK	0.002 OK	0.017
T1XX-FRT	mm	16:38:52	0.003 OK	0.002 OK	0.017
T1XX-FRT	mm	16:38:59	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	16:39:06	-0.005 OK	0.003 OK	0.01
T1XX-FRT	mm	16:39:24	0.002 OK	-0.004 OK	0.015
T1XX-FRT	mm	16:39:30	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	16:39:42	0 OK	-0.004 OK	0.012
T1XX-FRT	mm	16:39:48	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	16:39:55	0.004 OK	-0.003 OK	0.016
T1XX-FRT	mm	16:40:07	0.004 OK	-0.003 OK	0.016
T1XX-FRT	mm	16:40:18	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	16:40:31	0.003 OK	0.003 OK	0.019
T1XX-FRT	mm	16:40:38	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	16:40:57	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	16:41:03	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	16:41:22	0.005 OK	-0.002 OK	0.018
T1XX-FRT	mm	16:41:34	0.008 OK	-0.007 OK	0.019
T1XX-FRT	mm	16:41:47	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	16:41:59	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	16:42:14	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	16:42:20	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	16:42:39	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	16:42:51	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	16:43:09	0.001 OK	-0.002 OK	0.015

T1XX-FRT	mm	16:43:21	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	16:43:36	0.004 OK	-0.002 OK	0.016
T1XX-FRT	mm	16:43:48	-0.002 OK	-0.001 OK	0.012
T1XX-FRT	mm	16:44:01	-0.002 OK	-0.005 OK	0.009
T1XX-FRT	mm	16:44:12	0.002 OK	-0.004 OK	0.015
T1XX-FRT	mm	16:44:46	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	16:44:57	0 OK	-0.004 OK	0.012
T1XX-FRT	mm	16:45:14	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	16:45:20	0.004 OK	-0.005 OK	0.016
T1XX-FRT	mm	16:45:38	0.007 OK	-0.004 OK	0.019
T1XX-FRT	mm	16:45:50	-0.001 OK	0.002 OK	0.013
T1XX-FRT	mm	16:46:17	-0.001 OK	0.002 OK	0.013
T1XX-FRT	mm	16:46:28	0.001 OK	0 OK	0.015
T1XX-FRT	mm	16:46:34	0.005 OK	-0.002 OK	0.017
T1XX-FRT	mm	16:46:58	0.007 OK	-0.009 OK	0.016
T1XX-FRT	mm	16:47:09	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	16:47:20	0.004 OK	-0.005 OK	0.016
T1XX-FRT	mm	16:47:32	0.004 OK	-0.006 OK	0.016
T1XX-FRT	mm	16:47:38	0.013 NG	0.004 OK	0.023
T1XX-FRT	mm	16:47:50	0.005 OK	-0.003 OK	0.016
T1XX-FRT	mm	16:48:01	0.004 OK	-0.004 OK	0.016
T1XX-FRT	mm	16:48:11	0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:48:23	0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:49:08	0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:49:18	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	16:49:25	0.004 OK	-0.001 OK	0.017
T1XX-FRT	mm	16:49:32	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	16:49:38	0.002 OK	-0.004 OK	0.013
T1XX-FRT	mm	16:49:45	0.002 OK	0.004 OK	0.016
T1XX-FRT	mm	16:49:56	0.004 OK	-0.005 OK	0.015
T1XX-FRT	mm	16:50:07	-0.004 OK	-0.002 OK	0.01
T1XX-FRT	mm	16:50:14	0 OK	-0.004 OK	0.012
T1XX-FRT	mm	16:50:26	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	16:50:33	-0.001 OK	-0.002 OK	0.011
T1XX-FRT	mm	16:50:51	0.006 OK	-0.002 OK	0.016
T1XX-FRT	mm	16:51:02	-0.002 OK	-0.002 OK	0.01
T1XX-FRT	mm	16:51:16	0 OK	-0.001 OK	0.013
T1XX-FRT	mm	16:51:28	0.003 OK	-0.005 OK	0.015
T1XX-FRT	mm	16:51:41	0.003 OK	-0.006 OK	0.014
T1XX-FRT	mm	16:51:52	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	16:52:07	0.002 OK	-0.004 OK	0.013
T1XX-FRT	mm	16:52:18	0.003 OK	-0.004 OK	0.014
T1XX-FRT	mm	16:52:35	0.004 OK	-0.006 OK	0.015

T1XX-FRT	mm	16:52:47	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	16:53:04	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	16:53:15	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:53:44	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:53:54	0.009 OK	-0.006 OK	0.019
T1XX-FRT	mm	16:54:01	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	16:54:24	0.007 OK	-0.007 OK	0.018
T1XX-FRT	mm	16:54:36	0.005 OK	-0.006 OK	0.016
T1XX-FRT	mm	16:54:47	0.005 OK	-0.006 OK	0.015
T1XX-FRT	mm	16:55:05	0.006 OK	-0.008 OK	0.015
T1XX-FRT	mm	16:55:16	0.003 OK	0 OK	0.016
T1XX-FRT	mm	16:55:37	0.001 OK	-0.001 OK	0.014
T1XX-FRT	mm	16:55:48	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:56:26	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	16:56:36	0.001 OK	-0.001 OK	0.014
T1XX-FRT	mm	16:57:09	0.001 OK	-0.001 OK	0.014
T1XX-FRT	mm	16:57:16	-0.003 OK	-0.003 OK	0.009
T1XX-FRT	mm	16:57:44	0 OK	-0.004 OK	0.012
T1XX-FRT	mm	16:57:51	-0.001 OK	0.003 OK	0.014
T1XX-FRT	mm	16:58:02	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	16:58:53	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	16:58:59	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	16:59:11	0.001 OK	0.01 NG	0.016
T1XX-FRT	mm	16:59:17	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	16:59:24	0.001 OK	0.001 OK	0.015
T1XX-FRT	mm	16:59:30	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	16:59:42	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	16:59:54	0.004 OK	-0.001 OK	0.017
T1XX-FRT	mm	17:00:05	0.004 OK	-0.002 OK	0.017
T1XX-FRT	mm	17:00:17	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	17:00:28	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	17:00:39	0.004 OK	-0.002 OK	0.018
T1XX-FRT	mm	17:00:50	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	17:01:02	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	17:01:13	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	17:01:25	0.002 OK	-0.003 OK	0.014
T1XX-FRT	mm	17:01:36	0.008 OK	-0.004 OK	0.02
T1XX-FRT	mm	17:01:47	0.003 OK	-0.008 OK	0.013
T1XX-FRT	mm	17:01:59	0.008 OK	-0.009 OK	0.017
T1XX-FRT	mm	17:03:30	0.008 OK	-0.009 OK	0.017
T1XX-FRT	mm	17:03:38	0.01 OK	-0.006 OK	0.021
T1XX-FRT	mm	17:03:50	0.003 OK	-0.004 OK	0.015
T1XX-FRT	mm	17:03:56	0.006 OK	-0.005 OK	0.017

T1XX-FRT	mm	17:04:03	0.008 OK	0 OK	0.022
T1XX-FRT	mm	17:04:09	-0.001 OK	0.002 OK	0.012
T1XX-FRT	mm	17:04:17	-0.001 OK	-0.003 OK	0.01
T1XX-FRT	mm	17:04:23	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	17:06:19	0.007 OK	-0.004 OK	0.018
T1XX-FRT	mm	17:06:25	0.005 OK	-0.005 OK	0.017
T1XX-FRT	mm	17:06:54	-0.001 OK	-0.004 OK	0.011
T1XX-FRT	mm	17:07:00	0 OK	-0.005 OK	0.01
T1XX-FRT	mm	17:07:19	0.002 OK	-0.003 OK	0.013
T1XX-FRT	mm	17:07:26	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	17:07:44	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	17:07:50	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	17:08:09	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	17:08:16	0.002 OK	0 OK	0.016
T1XX-FRT	mm	17:08:34	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	17:08:45	0 OK	0.002 OK	0.015
T1XX-FRT	mm	17:08:59	0.01 OK	-0.003 OK	0.022
T1XX-FRT	mm	17:09:06	0.006 OK	-0.001 OK	0.019
T1XX-FRT	mm	17:09:24	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	17:09:30	0.004 OK	-0.001 OK	0.017
T1XX-FRT	mm	17:09:49	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	17:09:56	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	17:10:14	0.003 OK	-0.004 OK	0.015
T1XX-FRT	mm	17:10:20	0.005 OK	0 OK	0.019
T1XX-FRT	mm	17:10:39	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	17:10:45	0.002 OK	-0.004 OK	0.013
T1XX-FRT	mm	17:11:05	0.005 OK	-0.003 OK	0.018
T1XX-FRT	mm	17:11:11	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	17:11:29	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	17:11:35	0.007 OK	-0.002 OK	0.02
T1XX-FRT	mm	17:11:53	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	17:12:00	0.01 OK	-0.003 OK	0.022
T1XX-FRT	mm	17:12:19	0.01 OK	-0.003 OK	0.022
T1XX-FRT	mm	17:12:26	0.006 OK	-0.002 OK	0.019
T1XX-FRT	mm	17:12:43	0.004 OK	-0.002 OK	0.016
T1XX-FRT	mm	17:12:54	0.004 OK	-0.002 OK	0.017
T1XX-FRT	mm	17:13:09	0.006 OK	-0.002 OK	0.02
T1XX-FRT	mm	17:14:17	0.006 OK	-0.002 OK	0.02
T1XX-FRT	mm	17:14:23	0.01 OK	-0.006 OK	0.02
T1XX-FRT	mm	17:14:30	0.008 OK	-0.005 OK	0.019
T1XX-FRT	mm	17:14:43	0.007 OK	-0.005 OK	0.018
T1XX-FRT	mm	17:14:50	0.001 OK	0.008 OK	0.016
T1XX-FRT	mm	17:14:56	0.006 OK	-0.004 OK	0.018

T1XX-FRT	mm	17:15:03	0.003 OK	-0.004 OK	0.015
T1XX-FRT	mm	17:15:14	0.002 OK	0.001 OK	0.017
T1XX-FRT	mm	17:15:26	0.008 OK	-0.006 OK	0.019
T1XX-FRT	mm	17:15:36	0.008 OK	0.005 OK	0.02
T1XX-FRT	mm	17:15:43	0.007 OK	-0.005 OK	0.018
T1XX-FRT	mm	17:16:21	0.007 OK	-0.005 OK	0.018
T1XX-FRT	mm	17:16:28	0.012 NG	-0.009 OK	0.021
T1XX-FRT	mm	17:16:34	0.008 OK	-0.002 OK	0.02
T1XX-FRT	mm	17:16:47	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	17:16:54	0.003 OK	0.004 OK	0.02
T1XX-FRT	mm	17:17:00	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	17:17:07	0.005 OK	-0.004 OK	0.017
T1XX-FRT	mm	17:17:14	0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	17:17:21	0.007 OK	0 OK	0.019
T1XX-FRT	mm	17:17:27	0.004 OK	0.005 OK	0.022
T1XX-FRT	mm	17:17:49	0.007 OK	0.001 OK	0.021
T1XX-FRT	mm	17:17:56	0.001 OK	-0.001 OK	0.013
T1XX-FRT	mm	17:18:16	0.01 OK	-0.001 OK	0.021
T1XX-FRT	mm	17:18:27	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	17:18:41	0.002 OK	-0.004 OK	0.013
T1XX-FRT	mm	17:18:47	0.004 OK	0.006 OK	0.017
T1XX-FRT	mm	17:19:12	0 OK	0 OK	0.013
T1XX-FRT	mm	17:19:20	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	17:19:54	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	17:20:04	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	17:20:10	0 OK	0 OK	0.014
T1XX-FRT	mm	17:20:38	0 OK	0 OK	0.014
T1XX-FRT	mm	17:20:55	0.004 OK	-0.003 OK	0.015
T1XX-FRT	mm	17:21:12	-0.001 OK	-0.003 OK	0.01
T1XX-FRT	mm	17:21:24	0.008 OK	-0.005 OK	0.019
T1XX-FRT	mm	17:21:31	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	17:21:45	0.003 OK	0.004 OK	0.017
T1XX-FRT	mm	17:21:51	0.006 OK	-0.004 OK	0.016
T1XX-FRT	mm	17:22:18	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	17:22:24	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	17:22:43	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	17:22:50	0.006 OK	-0.002 OK	0.018
T1XX-FRT	mm	17:23:08	0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	17:23:14	0.002 OK	-0.003 OK	0.013
T1XX-FRT	mm	17:23:35	0.001 OK	-0.001 OK	0.014
T1XX-FRT	mm	17:23:47	0.007 OK	-0.005 OK	0.019
T1XX-FRT	mm	17:24:12	0.005 OK	-0.005 OK	0.016
T1XX-FRT	mm	17:24:18	0 OK	-0.002 OK	0.012

T1XX-FRT	mm	17:24:48	0.004 OK	-0.007 OK	0.015
T1XX-FRT	mm	17:24:54	0.005 OK	-0.006 OK	0.017
T1XX-FRT	mm	17:25:20	0.002 OK	0.003 OK	0.016
T1XX-FRT	mm	17:25:26	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	17:25:53	0.012 NG	0 OK	0.022
T1XX-FRT	mm	17:26:05	0.008 OK	-0.007 OK	0.018
T1XX-FRT	mm	17:26:28	0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	17:26:35	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	17:26:58	0.014 NG	-0.009 OK	0.022
T1XX-FRT	mm	17:27:05	0.005 OK	0.003 OK	0.019
T1XX-FRT	mm	17:27:32	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	17:28:41	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	17:28:47	0.004 OK	-0.004 OK	0.015
T1XX-FRT	mm	17:28:53	0.006 OK	0.004 OK	0.023
T1XX-FRT	mm	17:29:12	0.005 OK	-0.002 OK	0.017
T1XX-FRT	mm	17:29:23	0.002 OK	-0.001 OK	0.015
T1XX-FRT	mm	17:29:30	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	17:29:41	0.008 OK	0.002 OK	0.023
T1XX-FRT	mm	17:29:53	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	17:29:59	0.001 OK	0.006 OK	0.015
T1XX-FRT	mm	17:30:10	0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	17:30:21	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	17:30:43	0.006 OK	-0.003 OK	0.018
T1XX-FRT	mm	17:30:50	0.007 OK	0.007 OK	0.025
T1XX-FRT	mm	17:31:17	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	17:31:29	0.003 OK	0 OK	0.016
T1XX-FRT	mm	17:31:49	0.003 OK	-0.004 OK	0.015
T1XX-FRT	mm	17:31:56	0.008 OK	-0.004 OK	0.02
T1XX-FRT	mm	17:32:14	0.006 OK	-0.002 OK	0.018
T1XX-FRT	mm	17:32:20	0.003 OK	-0.001 OK	0.016
T1XX-FRT	mm	17:32:46	-0.001 OK	0.003 OK	0.012
T1XX-FRT	mm	17:32:52	0.005 OK	-0.002 OK	0.019
T1XX-FRT	mm	17:33:15	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	17:33:22	0.004 OK	-0.002 OK	0.016
T1XX-FRT	mm	17:33:44	0.003 OK	-0.001 OK	0.016
T1XX-FRT	mm	17:33:55	0.005 OK	0.002 OK	0.02
T1XX-FRT	mm	17:34:19	0.004 OK	0 OK	0.017
T1XX-FRT	mm	17:34:26	0.001 OK	0.001 OK	0.014
T1XX-FRT	mm	17:34:45	0.007 OK	-0.003 OK	0.019
T1XX-FRT	mm	17:34:51	0.004 OK	0.006 OK	0.022
T1XX-FRT	mm	17:35:13	0.007 OK	0.004 OK	0.023
T1XX-FRT	mm	17:35:45	0.007 OK	0.004 OK	0.023
T1XX-FRT	mm	17:35:56	0.007 OK	-0.003 OK	0.02

T1XX-FRT	mm	17:36:03	0.005 OK	-0.003 OK	0.016
T1XX-FRT	mm	17:36:16	-0.002 OK	-0.002 OK	0.011
T1XX-FRT	mm	17:36:22	0.006 OK	-0.007 OK	0.016
T1XX-FRT	mm	17:36:49	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	17:36:55	0.005 OK	-0.004 OK	0.018
T1XX-FRT	mm	17:37:17	0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	17:37:24	0.006 OK	-0.004 OK	0.019
T1XX-FRT	mm	17:37:52	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	17:37:59	0.006 OK	0.002 OK	0.021
T1XX-FRT	mm	17:38:17	0.007 OK	-0.006 OK	0.018
T1XX-FRT	mm	17:38:23	0.005 OK	0.001 OK	0.018
T1XX-FRT	mm	17:38:47	0.004 OK	-0.003 OK	0.015
T1XX-FRT	mm	17:38:54	0.002 OK	-0.003 OK	0.014
T1XX-FRT	mm	17:39:14	0.003 OK	-0.003 OK	0.014
T1XX-FRT	mm	17:39:25	0.01 OK	-0.006 OK	0.018
T1XX-FRT	mm	17:39:40	0.01 OK	0.007 OK	0.022
T1XX-FRT	mm	17:39:50	0.007 OK	-0.004 OK	0.019
T1XX-FRT	mm	17:40:08	0.003 OK	0.001 OK	0.018
T1XX-FRT	mm	17:40:19	0.004 OK	0.004 OK	0.018
T1XX-FRT	mm	17:40:39	0.002 OK	-0.003 OK	0.014
T1XX-FRT	mm	17:40:46	0.003 OK	-0.001 OK	0.016
T1XX-FRT	mm	17:41:07	0.005 OK	-0.002 OK	0.018
T1XX-FRT	mm	17:41:14	0.003 OK	-0.001 OK	0.015
T1XX-FRT	mm	17:42:31	0.002 OK	0.001 OK	0.016
T1XX-FRT	mm	17:42:52	0.007 OK	-0.002 OK	0.019
T1XX-FRT	mm	17:42:59	0.002 OK	-0.001 OK	0.015
T1XX-FRT	mm	17:43:05	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	17:43:22	0.004 OK	-0.002 OK	0.017
T1XX-FRT	mm	17:43:29	0.002 OK	-0.003 OK	0.013
T1XX-FRT	mm	17:43:48	0.003 OK	-0.002 OK	0.015
T1XX-FRT	mm	17:43:59	0.007 OK	-0.007 OK	0.017
T1XX-FRT	mm	17:44:12	0.004 OK	-0.003 OK	0.016
T1XX-FRT	mm	17:44:19	0.004 OK	-0.002 OK	0.016
T1XX-FRT	mm	17:44:38	0.003 OK	-0.002 OK	0.015
T1XX-FRT	mm	17:44:44	0.002 OK	-0.002 OK	0.014
T1XX-FRT	mm	17:45:05	0.002 OK	-0.001 OK	0.016
T1XX-FRT	mm	17:45:11	0.003 OK	-0.002 OK	0.017
T1XX-FRT	mm	17:45:29	0 OK	0.003 OK	0.014
T1XX-FRT	mm	17:45:40	0.001 OK	0.006 OK	0.015
T1XX-FRT	mm	17:45:57	0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	17:46:04	0.008 OK	-0.002 OK	0.02
T1XX-FRT	mm	17:46:22	0.005 OK	0.001 OK	0.021
T1XX-FRT	mm	17:46:28	0.005 OK	0.001 OK	0.019

T1XX-FRT	mm	17:46:53	0.003 OK	-0.002 OK	0.015
T1XX-FRT	mm	17:47:00	0.008 OK	-0.008 OK	0.018
T1XX-FRT	mm	17:47:22	0.004 OK	-0.002 OK	0.016
T1XX-FRT	mm	17:47:28	0.003 OK	0.001 OK	0.018
T1XX-FRT	mm	17:48:00	0.004 OK	-0.002 OK	0.016
T1XX-FRT	mm	17:48:46	0.004 OK	-0.002 OK	0.016
T1XX-FRT	mm	17:48:52	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	17:48:59	0 OK	0.005 OK	0.014
T1XX-FRT	mm	17:49:17	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	17:49:24	0.006 OK	-0.002 OK	0.019
T1XX-FRT	mm	17:49:31	0.005 OK	-0.002 OK	0.017
T1XX-FRT	mm	17:49:37	0.006 OK	-0.001 OK	0.019
T1XX-FRT	mm	17:49:56	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	17:50:03	0.001 OK	0.002 OK	0.014
T1XX-FRT	mm	17:50:26	0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	17:50:33	0.005 OK	-0.002 OK	0.018
T1XX-FRT	mm	17:50:58	0.005 OK	0.003 OK	0.02
T1XX-FRT	mm	17:51:04	0.006 OK	-0.002 OK	0.017
T1XX-FRT	mm	17:51:31	0.006 OK	-0.002 OK	0.018
T1XX-FRT	mm	17:51:43	0.007 OK	-0.003 OK	0.019
T1XX-FRT	mm	17:52:02	0.004 OK	-0.005 OK	0.015
T1XX-FRT	mm	17:52:08	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	17:52:28	0.01 OK	-0.006 OK	0.021
T1XX-FRT	mm	17:52:35	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	17:53:00	0.005 OK	-0.002 OK	0.017
T1XX-FRT	mm	17:53:07	0.002 OK	-0.001 OK	0.015
T1XX-FRT	mm	17:53:34	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	17:53:40	0.006 OK	-0.005 OK	0.018
T1XX-FRT	mm	17:53:58	0.008 OK	-0.008 OK	0.017
T1XX-FRT	mm	17:54:10	0.005 OK	-0.002 OK	0.018
T1XX-FRT	mm	17:54:25	0.004 OK	0 OK	0.017
T1XX-FRT	mm	17:54:32	0.008 OK	-0.004 OK	0.019
T1XX-FRT	mm	17:54:59	0.01 OK	-0.007 OK	0.02
T1XX-FRT	mm	17:55:10	0.006 OK	-0.003 OK	0.018
T1XX-FRT	mm	17:55:25	0.005 OK	-0.003 OK	0.018
T1XX-FRT	mm	17:55:33	0.008 OK	-0.004 OK	0.02
T1XX-FRT	mm	17:55:54	0.008 OK	-0.003 OK	0.019
T1XX-FRT	mm	17:56:01	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	17:56:28	0.011 NG	-0.003 OK	0.022
T1XX-FRT	mm	17:56:35	0 OK	-0.001 OK	0.013
T1XX-FRT	mm	17:56:57	0.004 OK	-0.003 OK	0.015
T1XX-FRT	mm	17:57:22	0.004 OK	-0.003 OK	0.015
T1XX-FRT	mm	17:57:33	0.001 OK	-0.001 OK	0.014

T1XX-FRT	mm	17:57:40	0.002 OK	-0.001 OK	0.015
T1XX-FRT	mm	17:58:00	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	17:58:12	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	17:58:26	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	17:58:33	0.007 OK	-0.004 OK	0.019
T1XX-FRT	mm	17:58:59	0.004 OK	-0.001 OK	0.016
T1XX-FRT	mm	17:59:05	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	17:59:28	0.005 OK	-0.005 OK	0.016
T1XX-FRT	mm	17:59:34	0.008 OK	-0.002 OK	0.021
T1XX-FRT	mm	18:00:05	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	18:00:12	-0.002 OK	-0.003 OK	0.01
T1XX-FRT	mm	18:00:31	0.01 OK	-0.003 OK	0.022
T1XX-FRT	mm	18:00:42	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	18:01:01	0.005 OK	-0.003 OK	0.016
T1XX-FRT	mm	18:01:07	0.002 OK	0.008 OK	0.017
T1XX-FRT	mm	18:01:29	0.003 OK	-0.002 OK	0.015
T1XX-FRT	mm	18:01:40	0.004 OK	0 OK	0.018
T1XX-FRT	mm	18:02:05	0.005 OK	-0.004 OK	0.016
T1XX-FRT	mm	18:02:16	0.007 OK	-0.003 OK	0.021
T1XX-FRT	mm	18:02:38	0.001 OK	-0.001 OK	0.014
T1XX-FRT	mm	18:02:44	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	18:03:03	0.007 OK	-0.008 OK	0.017
T1XX-FRT	mm	18:03:10	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	18:03:34	0.008 OK	-0.003 OK	0.019
T1XX-FRT	mm	18:03:40	0.004 OK	-0.003 OK	0.015
T1XX-FRT	mm	18:04:07	0.002 OK	-0.003 OK	0.014
T1XX-FRT	mm	18:04:18	0.004 OK	-0.003 OK	0.016
T1XX-FRT	mm	18:04:37	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	18:04:49	0.01 OK	-0.007 OK	0.02
T1XX-FRT	mm	18:05:07	0.008 OK	-0.005 OK	0.02
T1XX-FRT	mm	18:05:18	0.004 OK	-0.004 OK	0.016
T1XX-FRT	mm	18:05:40	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	18:05:52	0.001 OK	0 OK	0.014
T1XX-FRT	mm	18:06:08	0.002 OK	-0.003 OK	0.014
T1XX-FRT	mm	18:06:14	0.002 OK	0 OK	0.016
T1XX-FRT	mm	18:06:32	0.004 OK	-0.003 OK	0.016
T1XX-FRT	mm	18:06:44	0.009 OK	-0.002 OK	0.021
T1XX-FRT	mm	18:07:04	0.008 OK	-0.004 OK	0.02
T1XX-FRT	mm	18:07:10	0.011 NG	-0.007 OK	0.02
T1XX-FRT	mm	18:07:34	0.004 OK	-0.003 OK	0.016
T1XX-FRT	mm	18:07:45	0.005 OK	-0.002 OK	0.018
T1XX-FRT	mm	18:08:14	0.005 OK	-0.002 OK	0.018
T1XX-FRT	mm	18:08:24	0.001 OK	-0.002 OK	0.012

T1XX-FRT	mm	18:08:31	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	18:08:49	0.002 OK	-0.001 OK	0.015
T1XX-FRT	mm	18:09:11	0.008 OK	-0.002 OK	0.018
T1XX-FRT	mm	18:09:22	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	18:10:25	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	18:10:34	0.007 OK	-0.004 OK	0.018
T1XX-FRT	mm	18:10:41	0.01 OK	-0.004 OK	0.022
T1XX-FRT	mm	18:10:54	0 OK	-0.002 OK	0.013
T1XX-FRT	mm	18:11:01	0.001 OK	0.006 OK	0.016
T1XX-FRT	mm	18:11:07	0 OK	-0.003 OK	0.011
T1XX-FRT	mm	18:11:18	0.004 OK	-0.002 OK	0.017
T1XX-FRT	mm	18:11:25	0.005 OK	0.002 OK	0.021
T1XX-FRT	mm	18:11:36	0.008 OK	0.007 OK	0.023
T1XX-FRT	mm	18:11:47	0.002 OK	0.008 OK	0.017
T1XX-FRT	mm	18:12:02	0.002 OK	-0.003 OK	0.014
T1XX-FRT	mm	18:12:13	0.008 OK	-0.005 OK	0.019
T1XX-FRT	mm	18:12:33	0.001 OK	-0.005 OK	0.012
T1XX-FRT	mm	18:12:44	0.006 OK	-0.003 OK	0.019
T1XX-FRT	mm	18:12:58	0.01 OK	-0.006 OK	0.02
T1XX-FRT	mm	18:13:05	0.008 OK	-0.002 OK	0.02
T1XX-FRT	mm	18:13:27	0.008 OK	-0.004 OK	0.019
T1XX-FRT	mm	18:13:38	0.004 OK	0.001 OK	0.017
T1XX-FRT	mm	18:14:02	0.008 OK	-0.003 OK	0.02
T1XX-FRT	mm	18:14:14	0.006 OK	-0.003 OK	0.018
T1XX-FRT	mm	18:14:28	0.008 OK	-0.004 OK	0.02
T1XX-FRT	mm	18:14:35	0.006 OK	-0.004 OK	0.017
T1XX-FRT	mm	18:14:58	0.006 OK	-0.003 OK	0.018
T1XX-FRT	mm	18:15:08	0.005 OK	-0.003 OK	0.018
T1XX-FRT	mm	18:15:30	0.011 NG	-0.006 OK	0.02
T1XX-FRT	mm	18:15:41	0.001 OK	-0.002 OK	0.013
T1XX-FRT	mm	18:15:58	-0.001 OK	0.001 OK	0.013
T1XX-FRT	mm	18:16:09	0.007 OK	-0.005 OK	0.017
T1XX-FRT	mm	18:16:23	0.005 OK	-0.004 OK	0.015
T1XX-FRT	mm	18:16:31	0.006 OK	0.002 OK	0.02
T1XX-FRT	mm	18:16:55	0.007 OK	-0.002 OK	0.019
T1XX-FRT	mm	18:17:02	0.005 OK	0 OK	0.02
T1XX-FRT	mm	18:17:27	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	18:17:38	0.005 OK	-0.001 OK	0.018
T1XX-FRT	mm	18:17:52	0.003 OK	-0.002 OK	0.016
T1XX-FRT	mm	18:17:59	0.005 OK	-0.002 OK	0.017
T1XX-FRT	mm	18:18:25	0.015 NG	-0.008 OK	0.025
T1XX-FRT	mm	18:18:31	0.003 OK	-0.001 OK	0.016
T1XX-FRT	mm	18:18:59	0.015 NG	-0.01 OK	0.023

T1XX-FRT	mm	18:19:05	0.006 OK	-0.003 OK	0.018
T1XX-FRT	mm	18:20:13	0.004 OK	-0.003 OK	0.016
T1XX-FRT	mm	18:20:20	0.003 OK	-0.004 OK	0.015
T1XX-FRT	mm	18:20:46	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	18:20:52	0 OK	0.005 OK	0.015
T1XX-FRT	mm	18:21:11	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	18:21:22	0.002 OK	0.002 OK	0.017
T1XX-FRT	mm	18:21:50	0.002 OK	0.002 OK	0.017
T1XX-FRT	mm	18:21:57	0.005 OK	0 OK	0.018
T1XX-FRT	mm	18:22:04	0.001 OK	-0.004 OK	0.012
T1XX-FRT	mm	18:22:17	-0.002 OK	0.003 OK	0.012
T1XX-FRT	mm	18:22:28	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	18:22:40	0.007 OK	-0.005 OK	0.018
T1XX-FRT	mm	18:22:51	0.005 OK	0 OK	0.019
T1XX-FRT	mm	18:23:02	0.007 OK	-0.003 OK	0.019
T1XX-FRT	mm	18:23:16	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	18:23:22	-0.001 OK	0.005 OK	0.015
T1XX-FRT	mm	18:23:41	0.003 OK	-0.006 OK	0.013
T1XX-FRT	mm	18:23:48	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	18:24:16	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	18:24:26	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	18:24:32	0 OK	-0.002 OK	0.012
T1XX-FRT	mm	18:24:45	0.003 OK	-0.002 OK	0.015
T1XX-FRT	mm	18:24:56	0.004 OK	0.006 OK	0.018
T1XX-FRT	mm	18:25:02	0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	18:25:21	0.002 OK	-0.002 OK	0.014
T1XX-FRT	mm	18:25:28	0.002 OK	0 OK	0.017
T1XX-FRT	mm	18:25:49	-0.001 OK	-0.005 OK	0.01
T1XX-FRT	mm	18:26:00	0.003 OK	0.004 OK	0.016
T1XX-FRT	mm	18:26:21	0.002 OK	-0.005 OK	0.012
T1XX-FRT	mm	18:26:33	0.003 OK	-0.002 OK	0.017
T1XX-FRT	mm	18:26:49	0.005 OK	-0.002 OK	0.018
T1XX-FRT	mm	18:27:01	0.008 OK	-0.002 OK	0.021
T1XX-FRT	mm	18:27:22	0.01 OK	-0.006 OK	0.021
T1XX-FRT	mm	18:27:28	0.002 OK	0.006 OK	0.017
T1XX-FRT	mm	18:27:50	0.008 OK	-0.003 OK	0.02
T1XX-FRT	mm	18:27:56	0.007 OK	-0.005 OK	0.018
T1XX-FRT	mm	18:28:21	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	18:28:32	0.005 OK	-0.005 OK	0.016
T1XX-FRT	mm	18:28:52	0.006 OK	-0.003 OK	0.018
T1XX-FRT	mm	18:28:58	0.009 OK	-0.004 OK	0.021
T1XX-FRT	mm	18:29:19	0.007 OK	-0.005 OK	0.018
T1XX-FRT	mm	18:29:25	0.004 OK	-0.004 OK	0.016

T1XX-FRT	mm	18:29:43	0.003 OK	0.004 OK	0.016
T1XX-FRT	mm	18:29:50	0.006 OK	-0.004 OK	0.018
T1XX-FRT	mm	18:30:13	0.008 OK	-0.003 OK	0.019
T1XX-FRT	mm	18:30:20	0.007 OK	-0.004 OK	0.019
T1XX-FRT	mm	18:30:49	0.006 OK	-0.002 OK	0.019
T1XX-FRT	mm	18:31:00	0.007 OK	0.005 OK	0.021
T1XX-FRT	mm	18:31:14	0.006 OK	-0.003 OK	0.018
T1XX-FRT	mm	18:31:25	0.006 OK	-0.004 OK	0.018
T1XX-FRT	mm	18:31:40	0.007 OK	-0.003 OK	0.019
T1XX-FRT	mm	18:31:51	0.003 OK	-0.005 OK	0.015
T1XX-FRT	mm	18:32:20	0.004 OK	0.005 OK	0.022
T1XX-FRT	mm	18:32:32	0.005 OK	0.001 OK	0.02
T1XX-FRT	mm	18:32:45	0.006 OK	-0.007 OK	0.017
T1XX-FRT	mm	18:32:56	0.003 OK	0.005 OK	0.019
T1XX-FRT	mm	18:33:13	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	18:34:21	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	18:34:28	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	18:34:34	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	18:34:57	-0.001 OK	-0.003 OK	0.011
T1XX-FRT	mm	18:35:04	0.001 OK	0 OK	0.015
T1XX-FRT	mm	18:35:16	-0.001 OK	-0.002 OK	0.012
T1XX-FRT	mm	18:35:27	0.004 OK	-0.004 OK	0.016
T1XX-FRT	mm	18:35:38	0.007 OK	-0.005 OK	0.018
T1XX-FRT	mm	18:35:50	0.006 OK	-0.004 OK	0.019
T1XX-FRT	mm	18:36:01	0.008 OK	-0.004 OK	0.02
T1XX-FRT	mm	18:36:08	0.005 OK	-0.003 OK	0.017
T1XX-FRT	mm	18:36:19	0.003 OK	-0.002 OK	0.018
T1XX-FRT	mm	18:36:30	0.005 OK	0.005 OK	0.019
T1XX-FRT	mm	18:36:41	0.007 OK	-0.002 OK	0.021
T1XX-FRT	mm	18:36:53	0.006 OK	0.001 OK	0.021
T1XX-FRT	mm	18:37:14	0.003 OK	-0.002 OK	0.017
T1XX-FRT	mm	18:37:20	0.008 OK	0.003 OK	0.021
T1XX-FRT	mm	18:37:40	0.009 OK	-0.005 OK	0.021
T1XX-FRT	mm	18:37:51	0.007 OK	-0.003 OK	0.02
T1XX-FRT	mm	18:38:12	0.008 OK	0 OK	0.021
T1XX-FRT	mm	18:38:23	0.004 OK	0.001 OK	0.019
T1XX-FRT	mm	18:38:43	0.009 OK	-0.002 OK	0.023
T1XX-FRT	mm	18:38:49	0.014 NG	-0.007 OK	0.025
T1XX-FRT	mm	18:39:16	0.002 OK	-0.004 OK	0.016
T1XX-FRT	mm	18:39:23	0.003 OK	-0.003 OK	0.015
T1XX-FRT	mm	18:39:51	0.01 OK	-0.002 OK	0.023
T1XX-FRT	mm	18:40:02	0.006 OK	-0.001 OK	0.02
T1XX-FRT	mm	18:40:17	0.016 NG	-0.005 OK	0.025

T1XX-FRT	mm	18:40:29	0.006 OK	0.006 OK	0.022
T1XX-FRT	mm	18:40:49	0.006 OK	-0.003 OK	0.019
T1XX-FRT	mm	18:41:00	0.005 OK	-0.004 OK	0.018
T1XX-FRT	mm	18:41:18	0.006 OK	-0.002 OK	0.02
T1XX-FRT	mm	18:41:29	0.007 OK	0.006 OK	0.021
T1XX-FRT	mm	18:41:47	0.009 OK	-0.002 OK	0.022
T1XX-FRT	mm	18:41:59	0.008 OK	0.002 OK	0.024
T1XX-FRT	mm	18:44:41	0.005 OK	-0.002 OK	0.019
T1XX-FRT	mm	18:44:53	0.008 OK	-0.003 OK	0.022
T1XX-FRT	mm	18:44:59	0.003 OK	-0.002 OK	0.017
T1XX-FRT	mm	18:45:11	0.008 OK	-0.002 OK	0.022
T1XX-FRT	mm	18:45:23	0.003 OK	-0.003 OK	0.016
T1XX-FRT	mm	18:45:30	0.006 OK	0.003 OK	0.022
T1XX-FRT	mm	18:45:36	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	18:45:48	0.005 OK	-0.003 OK	0.019
T1XX-FRT	mm	18:45:59	0.006 OK	-0.003 OK	0.019
T1XX-FRT	mm	18:46:11	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	18:46:17	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	18:46:24	0.008 OK	-0.002 OK	0.019
T1XX-FRT	mm	18:46:31	0.006 OK	-0.005 OK	0.018
T1XX-FRT	mm	18:46:43	0.009 OK	-0.004 OK	0.022
T1XX-FRT	mm	18:46:54	0.004 OK	-0.003 OK	0.017
T1XX-FRT	mm	18:47:05	0 OK	0 OK	0.015
T1XX-FRT	mm	18:47:16	-0.002 OK	-0.004 OK	0.012
T1XX-FRT	mm	18:47:28	-0.001 OK	-0.004 OK	0.012
T1XX-FRT	mm	18:47:40	-0.001 OK	-0.004 OK	0.012
T1XX-FRT	mm	18:47:46	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	18:47:58	0.008 OK	-0.008 OK	0.019
T1XX-FRT	mm	18:48:09	-0.005 OK	-0.005 OK	0.008
T1XX-FRT	mm	18:48:20	0.002 OK	-0.006 OK	0.014
T1XX-FRT	mm	18:48:27	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	18:48:59	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	18:49:10	-0.002 OK	-0.001 OK	0.013
T1XX-FRT	mm	18:49:17	0 OK	-0.005 OK	0.013
T1XX-FRT	mm	18:49:58	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	18:50:05	-0.003 OK	0.004 OK	0.012
T1XX-FRT	mm	18:50:23	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	18:50:55	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	18:51:06	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	18:53:25	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	18:53:31	0 OK	-0.005 OK	0.012
T1XX-FRT	mm	18:53:50	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	18:54:02	0 OK	0.002 OK	0.015

T1XX-FRT	mm	18:54:13	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	18:54:25	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	18:54:37	0 OK	-0.005 OK	0.012
T1XX-FRT	mm	18:54:48	0.003 OK	-0.005 OK	0.014
T1XX-FRT	mm	18:54:55	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	18:55:06	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	18:55:13	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	18:55:24	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	18:55:31	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	18:55:42	0.004 OK	-0.005 OK	0.016
T1XX-FRT	mm	18:55:53	0.004 OK	-0.003 OK	0.016
T1XX-FRT	mm	18:56:05	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	18:56:11	-0.004 OK	-0.003 OK	0.01
T1XX-FRT	mm	18:56:23	-0.002 OK	-0.004 OK	0.012
T1XX-FRT	mm	18:56:35	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	18:56:47	-0.006 OK	0.003 OK	0.009
T1XX-FRT	mm	18:56:58	0.003 OK	-0.004 OK	0.015
T1XX-FRT	mm	18:57:05	0.005 OK	-0.005 OK	0.016
T1XX-FRT	mm	18:57:16	-0.001 OK	-0.004 OK	0.012
T1XX-FRT	mm	18:58:36	0.001 OK	-0.002 OK	0.016
T1XX-FRT	mm	18:58:48	0.002 OK	0.004 OK	0.017
T1XX-FRT	mm	18:59:01	0.003 OK	-0.004 OK	0.016
T1XX-FRT	mm	18:59:13	0.01 OK	-0.007 OK	0.022
T1XX-FRT	mm	18:59:26	-0.003 OK	-0.004 OK	0.01
T1XX-FRT	mm	18:59:38	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	18:59:52	-0.001 OK	-0.005 OK	0.011
T1XX-FRT	mm	18:59:58	0.003 OK	-0.002 OK	0.017
T1XX-FRT	mm	19:00:17	0.006 OK	-0.006 OK	0.017
T1XX-FRT	mm	19:00:28	0.01 OK	-0.006 OK	0.022
T1XX-FRT	mm	19:00:41	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	19:00:53	0.001 OK	-0.004 OK	0.015
T1XX-FRT	mm	19:01:07	-0.002 OK	0 OK	0.013
T1XX-FRT	mm	19:01:18	0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	19:01:32	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	19:01:44	0.002 OK	0.004 OK	0.02
T1XX-FRT	mm	19:01:57	0 OK	-0.002 OK	0.015
T1XX-FRT	mm	19:02:03	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	19:02:22	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	19:02:34	-0.002 OK	-0.002 OK	0.013
T1XX-FRT	mm	19:03:04	-0.002 OK	-0.004 OK	0.011
T1XX-FRT	mm	19:03:16	0.001 OK	0.001 OK	0.017
T1XX-FRT	mm	19:03:22	0 OK	-0.004 OK	0.013
T1XX-FRT	mm	19:03:29	0.001 OK	-0.002 OK	0.015

T1XX-FRT	mm	19:03:40	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	19:03:51	0 OK	0.004 OK	0.015
T1XX-FRT	mm	19:04:03	0.003 OK	-0.002 OK	0.015
T1XX-FRT	mm	19:04:14	0.004 OK	0.003 OK	0.021
T1XX-FRT	mm	19:04:26	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	19:04:38	0.006 OK	-0.004 OK	0.02
T1XX-FRT	mm	19:04:52	0.003 OK	-0.004 OK	0.016
T1XX-FRT	mm	19:04:58	0.005 OK	-0.004 OK	0.019
T1XX-FRT	mm	19:05:46	0.005 OK	-0.004 OK	0.019
T1XX-FRT	mm	19:05:55	0.002 OK	-0.004 OK	0.015
T1XX-FRT	mm	19:06:02	0.001 OK	-0.001 OK	0.016
T1XX-FRT	mm	19:06:13	0.009 OK	-0.01 OK	0.019
T1XX-FRT	mm	19:06:20	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	19:06:26	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	19:06:33	-0.003 OK	0.005 OK	0.013
T1XX-FRT	mm	19:06:40	0.005 OK	-0.001 OK	0.018
T1XX-FRT	mm	19:06:46	-0.002 OK	-0.004 OK	0.011
T1XX-FRT	mm	19:06:57	-0.001 OK	0.003 OK	0.016
T1XX-FRT	mm	19:07:03	0.004 OK	-0.007 OK	0.015
T1XX-FRT	mm	19:07:21	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	19:07:28	0.006 OK	-0.005 OK	0.018
T1XX-FRT	mm	19:07:47	0.005 OK	-0.004 OK	0.019
T1XX-FRT	mm	19:07:53	0.005 OK	-0.004 OK	0.019
T1XX-FRT	mm	19:08:12	0.005 OK	0.005 OK	0.02
T1XX-FRT	mm	19:08:19	0.003 OK	-0.001 OK	0.017
T1XX-FRT	mm	19:08:37	0.005 OK	0.001 OK	0.02
T1XX-FRT	mm	19:08:44	-0.002 OK	-0.004 OK	0.01
T1XX-FRT	mm	19:09:11	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	19:09:17	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	19:09:43	-0.002 OK	-0.003 OK	0.012
T1XX-FRT	mm	19:09:49	-0.001 OK	0.004 OK	0.014
T1XX-FRT	mm	19:10:15	-0.002 OK	-0.004 OK	0.011
T1XX-FRT	mm	19:10:21	0.004 OK	-0.006 OK	0.016
T1XX-FRT	mm	19:10:40	0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	19:10:47	0.002 OK	-0.002 OK	0.017
T1XX-FRT	mm	19:11:10	0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	19:11:16	0.004 OK	-0.002 OK	0.018
T1XX-FRT	mm	19:11:39	0.004 OK	-0.005 OK	0.016
T1XX-FRT	mm	19:11:50	0.001 OK	-0.004 OK	0.015
T1XX-FRT	mm	19:12:14	0.005 OK	-0.004 OK	0.017
T1XX-FRT	mm	19:13:02	0.005 OK	-0.004 OK	0.017
T1XX-FRT	mm	19:13:09	0.001 OK	-0.002 OK	0.016
T1XX-FRT	mm	19:13:15	-0.003 OK	-0.003 OK	0.012

T1XX-FRT	mm	19:13:29	-0.003 OK	-0.002 OK	0.01
T1XX-FRT	mm	19:13:35	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	19:13:45	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	19:13:51	-0.002 OK	-0.004 OK	0.011
T1XX-FRT	mm	19:14:23	-0.003 OK	-0.002 OK	0.011
T1XX-FRT	mm	19:14:30	0.002 OK	-0.002 OK	0.016
T1XX-FRT	mm	19:14:50	0.01 OK	-0.005 OK	0.023
T1XX-FRT	mm	19:14:57	0.006 OK	-0.001 OK	0.022
T1XX-FRT	mm	19:15:15	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	19:16:52	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	19:17:04	0.007 OK	0.004 OK	0.025
T1XX-FRT	mm	19:17:10	0.003 OK	0.007 OK	0.019
T1XX-FRT	mm	19:17:23	0.008 OK	-0.004 OK	0.021
T1XX-FRT	mm	19:17:30	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	19:17:36	0 OK	-0.003 OK	0.013
T1XX-FRT	mm	19:17:43	-0.002 OK	-0.003 OK	0.011
T1XX-FRT	mm	19:17:49	0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	19:17:56	0.002 OK	-0.004 OK	0.016
T1XX-FRT	mm	19:18:07	0.003 OK	-0.004 OK	0.015
T1XX-FRT	mm	19:18:14	0.002 OK	-0.003 OK	0.015
T1XX-FRT	mm	19:18:20	0.013 NG	-0.008 OK	0.023
T1XX-FRT	mm	19:18:32	0.002 OK	0.005 OK	0.018
T1XX-FRT	mm	19:18:54	0.001 OK	0.005 OK	0.017
T1XX-FRT	mm	19:19:01	0.006 OK	-0.002 OK	0.02
T1XX-FRT	mm	19:19:29	0.004 OK	-0.002 OK	0.017
T1XX-FRT	mm	19:19:40	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	19:20:00	-0.003 OK	-0.003 OK	0.011
T1XX-FRT	mm	19:20:11	0.001 OK	0.008 OK	0.016
T1XX-FRT	mm	19:20:18	0.005 OK	-0.003 OK	0.019
T1XX-FRT	mm	19:20:35	0.002 OK	-0.002 OK	0.015
T1XX-FRT	mm	19:20:58	-0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	19:21:10	0.01 OK	-0.008 OK	0.021
T1XX-FRT	mm	19:21:25	0.005 OK	-0.003 OK	0.02
T1XX-FRT	mm	19:21:32	0.005 OK	-0.003 OK	0.018
T1XX-FRT	mm	19:21:56	-0.006 OK	-0.003 OK	0.007
T1XX-FRT	mm	19:22:03	-0.004 OK	0.002 OK	0.011
T1XX-FRT	mm	19:22:21	-0.002 OK	-0.004 OK	0.011
T1XX-FRT	mm	19:22:32	-0.002 OK	-0.002 OK	0.012
T1XX-FRT	mm	19:22:56	0.006 OK	-0.007 OK	0.018
T1XX-FRT	mm	19:23:02	0.004 OK	-0.002 OK	0.017
T1XX-FRT	mm	19:23:25	-0.001 OK	-0.003 OK	0.012
T1XX-FRT	mm	19:23:38	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	19:23:54	0.004 OK	-0.003 OK	0.017

T1XX-FRT	mm	19:24:00	0.008 OK	-0.006 OK	0.02
T1XX-FRT	mm	19:24:28	0.005 OK	-0.003 OK	0.019
T1XX-FRT	mm	19:24:41	0.001 OK	0.004 OK	0.017
T1XX-FRT	mm	19:24:59	0.009 OK	-0.004 OK	0.022
T1XX-FRT	mm	19:25:05	0.007 OK	0.002 OK	0.024
T1XX-FRT	mm	19:34:35	0.004 OK	-0.002 OK	0.02
T1XX-FRT	mm	19:34:41	-0.003 OK	-0.003 OK	0.01
T1XX-FRT	mm	19:35:11	0.002 OK	-0.003 OK	0.017
T1XX-FRT	mm	19:35:22	0.007 OK	-0.009 OK	0.018
T1XX-FRT	mm	19:35:48	0.001 OK	-0.004 OK	0.013
T1XX-FRT	mm	19:35:54	-0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	19:36:32	0 OK	-0.004 OK	0.014
T1XX-FRT	mm	19:36:38	-0.001 OK	-0.002 OK	0.015
T1XX-FRT	mm	19:36:57	0.005 OK	-0.003 OK	0.019
T1XX-FRT	mm	19:37:03	0.005 OK	-0.002 OK	0.019
T1XX-FRT	mm	19:37:22	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	19:37:55	0.002 OK	-0.004 OK	0.014
T1XX-FRT	mm	19:38:01	0.003 OK	-0.003 OK	0.018
T1XX-FRT	mm	19:38:07	0.008 OK	-0.004 OK	0.022
T1XX-FRT	mm	19:38:26	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	19:38:37	0.003 OK	-0.004 OK	0.016
T1XX-FRT	mm	19:38:47	0.008 OK	-0.002 OK	0.022
T1XX-FRT	mm	19:38:59	-0.02 NG	-0.006 OK	-0.009
T1XX-FRT	mm	19:39:10	-0.019 NG	-0.007 OK	-0.008
T1XX-FRT	mm	19:39:21	-0.013 NG	-0.008 OK	-0.003
T1XX-FRT	mm	19:39:33	-0.02 NG	-0.006 OK	-0.008
T1XX-FRT	mm	19:39:40	-0.016 NG	-0.009 OK	-0.007
T1XX-FRT	mm	19:39:52	-0.003 OK	-0.004 OK	0.009
T1XX-FRT	mm	19:40:26	-0.003 OK	-0.004 OK	0.009
T1XX-FRT	mm	19:40:32	-0.009 OK	-0.004 OK	0.003
T1XX-FRT	mm	19:40:43	-0.008 OK	-0.003 OK	0.005
T1XX-FRT	mm	19:40:56	-0.012 NG	-0.002 OK	0.002
T1XX-FRT	mm	19:41:08	-0.002 OK	-0.004 OK	0.007
T1XX-FRT	mm	19:41:20	-0.009 OK	-0.003 OK	0.004
T1XX-FRT	mm	19:41:26	-0.01 OK	0.001 OK	0.004
T1XX-FRT	mm	19:41:37	-0.009 OK	-0.004 OK	0.003
T1XX-FRT	mm	19:41:50	-0.008 OK	-0.005 OK	0.004
T1XX-FRT	mm	8:00:37	-0.008 OK	-0.005 OK	0.004
T1XX-FRT	mm	8:01:22	-0.009 OK	0.001 OK	0.007
T1XX-FRT	mm	8:01:30	-0.008 OK	-0.005 OK	0.005
T1XX-FRT	mm	8:01:50	-0.009 OK	-0.004 OK	0.006
T1XX-FRT	mm	8:01:57	-0.01 OK	-0.003 OK	0.005
T1XX-FRT	mm	8:02:15	-0.012 NG	-0.006 OK	0.001

T1XX-FRT	mm	8:02:26	-0.008 OK	-0.004 OK	0.007
T1XX-FRT	mm	8:06:43	-0.013 NG	0.002 OK	0.003
T1XX-FRT	mm	8:06:49	-0.014 NG	-0.004 OK	0
T1XX-FRT	mm	8:07:14	-0.007 OK	-0.006 OK	0.007
T1XX-FRT	mm	8:07:26	-0.01 OK	-0.004 OK	0.005
T1XX-FRT	mm	8:07:40	-0.014 NG	-0.004 OK	0
T1XX-FRT	mm	8:07:47	-0.012 NG	-0.004 OK	0.002
T1XX-FRT	mm	8:09:07	-0.002 OK	-0.008 OK	0.009
T1XX-FRT	mm	8:09:13	-0.008 OK	-0.005 OK	0.005
T1XX-FRT	mm	8:09:36	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	8:10:34	0.001 OK	-0.003 OK	0.015
T1XX-FRT	mm	8:10:41	0.008 OK	-0.004 OK	0.023
T1XX-FRT	mm	8:10:47	0.011 NG	0 OK	0.025
T1XX-FRT	mm	8:11:00	0.005 OK	-0.004 OK	0.019
T1XX-FRT	mm	8:11:07	0 OK	-0.002 OK	0.014
T1XX-FRT	mm	8:11:36	0 OK	-0.002 OK	0.016
T1XX-FRT	mm	8:11:42	0.007 OK	-0.004 OK	0.021
T1XX-FRT	mm	8:12:03	0.008 OK	-0.006 OK	0.021
T1XX-FRT	mm	8:12:09	-0.009 OK	-0.005 OK	0.004
T1XX-FRT	mm	8:12:28	-0.008 OK	-0.004 OK	0.005
T1XX-FRT	mm	8:12:35	-0.008 OK	-0.006 OK	0.005
T1XX-FRT	mm	8:13:02	-0.008 OK	0 OK	0.008
T1XX-FRT	mm	8:13:08	-0.004 OK	-0.006 OK	0.008
T1XX-FRT	mm	8:13:28	-0.006 OK	-0.003 OK	0.009
T1XX-FRT	mm	8:13:39	-0.004 OK	0.003 OK	0.01
T1XX-FRT	mm	8:13:53	-0.004 OK	-0.005 OK	0.009
T1XX-FRT	mm	8:14:04	-0.007 OK	-0.002 OK	0.008
T1XX-FRT	mm	8:14:28	-0.009 OK	-0.004 OK	0.005
T1XX-FRT	mm	8:14:39	-0.003 OK	0.003 OK	0.011
T1XX-FRT	mm	8:15:19	-0.005 OK	-0.005 OK	0.008
T1XX-FRT	mm	8:15:29	-0.002 OK	-0.005 OK	0.012
T1XX-FRT	mm	8:17:00	-0.002 OK	-0.005 OK	0.012
T1XX-FRT	mm	8:17:10	-0.008 OK	-0.004 OK	0.005
T1XX-FRT	mm	8:17:16	0.003 OK	-0.006 OK	0.016
T1XX-FRT	mm	8:17:23	-0.009 OK	-0.003 OK	0.005
T1XX-FRT	mm	8:17:30	-0.009 OK	0 OK	0.006
T1XX-FRT	mm	8:18:28	-0.006 OK	-0.004 OK	0.007
T1XX-FRT	mm	8:18:39	-0.006 OK	-0.006 OK	0.007
T1XX-FRT	mm	8:18:50	-0.009 OK	-0.004 OK	0.004
T1XX-FRT	mm	8:18:57	-0.014 NG	0.001 OK	0.001
T1XX-FRT	mm	8:19:03	-0.015 NG	-0.003 OK	-0.001
T1XX-FRT	mm	8:19:10	-0.009 OK	-0.004 OK	0.005
T1XX-FRT	mm	8:19:25	-0.01 OK	-0.003 OK	0.005

T1XX-FRT	mm	8:19:31	-0.009 OK	-0.003 OK	0.005
T1XX-FRT	mm	8:20:01	-0.013 NG	0.001 OK	0.002
T1XX-FRT	mm	8:20:12	-0.009 OK	-0.005 OK	0.004
T1XX-FRT	mm	8:20:32	-0.011 NG	0.001 OK	0.006
T1XX-FRT	mm	8:20:42	-0.01 OK	-0.004 OK	0.004
T1XX-FRT	mm	8:21:13	-0.008 OK	-0.003 OK	0.006
T1XX-FRT	mm	8:21:19	-0.014 NG	-0.004 OK	0.001
T1XX-FRT	mm	8:21:40	-0.012 NG	-0.001 OK	0.003
T1XX-FRT	mm	8:21:46	-0.009 OK	-0.004 OK	0.005
T1XX-FRT	mm	8:22:12	-0.009 OK	-0.005 OK	0.005
T1XX-FRT	mm	8:22:24	-0.01 OK	-0.004 OK	0.004
T1XX-FRT	mm	8:22:41	-0.005 OK	-0.005 OK	0.009
T1XX-FRT	mm	8:22:52	-0.013 NG	-0.004 OK	0.001
T1XX-FRT	mm	8:23:15	-0.013 NG	0.001 OK	0.004
T1XX-FRT	mm	8:23:21	-0.013 NG	-0.002 OK	0
T1XX-FRT	mm	8:23:44	-0.009 OK	-0.006 OK	0.004
T1XX-FRT	mm	8:23:50	-0.01 OK	-0.003 OK	0.005
T1XX-FRT	mm	8:24:21	-0.012 NG	-0.005 OK	0
T1XX-FRT	mm	8:24:27	-0.009 OK	-0.004 OK	0.005
T1XX-FRT	mm	8:24:53	-0.009 OK	-0.005 OK	0.004
T1XX-FRT	mm	8:25:00	-0.007 OK	-0.003 OK	0.008
T1XX-FRT	mm	8:25:22	-0.005 OK	-0.003 OK	0.009
T1XX-FRT	mm	8:25:29	-0.001 OK	-0.006 OK	0.013
T1XX-FRT	mm	8:25:53	0.001 OK	0.003 OK	0.016
T1XX-FRT	mm	8:26:00	0 OK	-0.003 OK	0.014
T1XX-FRT	mm	8:26:22	0 OK	-0.003 OK	0.015
T1XX-FRT	mm	8:26:30	-0.001 OK	-0.003 OK	0.014
T1XX-FRT	mm	8:26:55	-0.003 OK	0 OK	0.012
T1XX-FRT	mm	8:27:20	-0.003 OK	0 OK	0.012
T1XX-FRT	mm	8:27:27	0 OK	0.008 OK	0.017
T1XX-FRT	mm	8:27:33	-0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	8:27:55	-0.001 OK	-0.003 OK	0.013
T1XX-FRT	mm	8:28:02	0 OK	-0.001 OK	0.015
T1XX-FRT	mm	8:28:22	-0.001 OK	-0.004 OK	0.014
T1XX-FRT	mm	8:28:28	0.006 OK	-0.008 OK	0.017
T1XX-FRT	mm	8:28:57	0.002 OK	-0.003 OK	0.016
T1XX-FRT	mm	8:29:04	-0.004 OK	-0.003 OK	0.012
T1XX-FRT	mm	8:29:22	-0.001 OK	-0.002 OK	0.014
T1XX-FRT	mm	8:29:28	0.006 OK	-0.009 OK	0.019

판 정	궤도경	판 정	외관A	판 정	외관B	판 정
OK	-0.002	OK	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK	OK
OK	0	OK	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK	OK
OK	-0.023	OK	OK	OK	OK	OK
OK	-0.028	OK	OK	OK	OK	OK
OK	-0.089	NG	OK	OK	OK	OK
OK	-0.034	NG	OK	OK	OK	OK
OK	-0.034	NG	OK	OK	OK	OK
OK	-0.055	NG	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK	OK
OK	-0.01	OK	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK	OK
OK	-0.014	OK	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK	OK
OK	-0.082	NG	OK	OK	OK	OK
OK	-0.057	NG	OK	OK	OK	OK
OK	-0.072	NG	OK	OK	OK	OK
OK	-0.081	NG	OK	OK	OK	OK
OK	-0.038	NG	OK	OK	OK	OK
OK	-0.043	NG	OK	OK	OK	OK
OK	-0.37	NG	OK	OK	OK	OK
OK	-0.37	NG	OK	OK	OK	OK
OK	-0.022	OK	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK	OK

OK	-0.009 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.032 NG	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.075 NG	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.075 NG	OK	OK	OK	OK
OK	-0.075 NG	OK	OK	OK	OK
OK	-0.035 NG	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.066 NG	OK	OK	OK	OK

OK	-0.002 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.042 NG	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.051 NG	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.055 NG	OK	OK	OK	OK
OK	-0.046 NG	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK

OK	-0.002	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.013	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	-0.012	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK

OK	-0.01	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.015	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.012	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	0.011	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	0.014	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK

OK	0.004	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.011	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	-0.02	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	0.022	OK	OK	OK	OK
OK	0.022	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK

OK	0.002	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	-0.013	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.011	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.011	OK	OK	OK	OK
OK	0.011	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK

OK	0.007	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.011	OK	OK	OK	OK
OK	0.015	OK	OK	OK	OK
OK	0.015	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	0.011	OK	OK	OK	OK
OK	0.012	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	-0.01	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.023	OK	OK	OK	OK
OK	-0.014	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	-0.01	OK	OK	OK	OK
OK	0.004	NG	NG	OK	OK

OK	0.004 OK	NG	NG	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	-0.039 NG	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	-0.082 NG	OK	OK	OK	OK
OK	-0.079 NG	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK

OK	-0.029 OK	OK	OK	OK	OK
OK	-0.103 NG	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.219 NG	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK

OK	-0.012	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	-0.022	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.014	OK	OK	OK	OK
OK	-0.01	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.014	OK	OK	OK	OK
OK	-0.015	OK	OK	OK	OK
OK	-0.02	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.015	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.05	NG	OK	OK	OK
OK	-0.035	NG	OK	OK	OK
OK	-0.01	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK
OK	-0.025	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.027	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	-0.023	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.078	NG	OK	OK	OK
OK	-0.028	OK	OK	OK	OK
OK	-0.014	OK	OK	OK	OK
OK	-0.011	OK	OK	OK	OK
OK	-0.044	NG	OK	OK	OK
OK	-0.013	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.016	OK	OK	OK	OK

OK	0.004 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.015 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.031 NG	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.036 NG	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK

OK	-0.091 NG	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.08 NG	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.083 NG	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.037 NG	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.051 NG	OK	OK	OK	OK
OK	-0.051 NG	OK	OK	OK	OK
OK	-0.051 NG	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK

OK	-0.011 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.132 NG	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.046 NG	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.05 NG	OK	OK	OK	OK
OK	-0.359 NG	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.245 NG	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.09 NG	OK	OK	OK	OK
OK	-0.092 NG	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.031 NG	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK

OK	-0.017 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.058 NG	OK	OK	OK	OK
OK	-0.09 NG	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.054 NG	OK	OK	OK	OK
OK	-0.054 NG	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.217 NG	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.045 NG	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.045 NG	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.032 NG	OK	OK	OK	OK
OK	-0.032 NG	OK	OK	OK	OK

OK	-0.06 NG	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	-0.052 NG	OK	OK	OK	OK
OK	-0.104 NG	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.084 NG	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.094 NG	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.096 NG	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	-0.104 NG	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.077 NG	OK	OK	OK	OK
OK	-0.135 NG	OK	OK	OK	OK
OK	-0.053 NG	OK	OK	OK	OK
OK	-0.048 NG	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK

OK	-0.016 OK	OK	OK	OK	OK
OK	-0.07 NG	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.119 NG	OK	OK	OK	OK
OK	-0.145 NG	OK	OK	OK	OK
OK	-0.039 NG	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.076 NG	OK	OK	OK	OK
OK	-0.038 NG	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.047 NG	OK	OK	OK	OK
OK	-0.047 NG	OK	OK	OK	OK
OK	-0.036 NG	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.105 NG	OK	OK	OK	OK
OK	-0.063 NG	OK	OK	OK	OK
OK	-0.113 NG	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK

OK	0.01 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.262 NG	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.15 NG	OK	OK	OK	OK
OK	-0.085 NG	OK	OK	OK	OK
OK	-0.126 NG	OK	OK	OK	OK
OK	-0.126 NG	OK	OK	OK	OK
OK	-0.363 NG	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.032 NG	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.085 NG	OK	OK	OK	OK
OK	-0.103 NG	OK	OK	OK	OK
OK	-0.209 NG	OK	OK	OK	OK
OK	-0.367 NG	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.184 NG	OK	OK	OK	OK
OK	-0.184 NG	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.059 NG	OK	OK	OK	OK
OK	-0.059 NG	OK	OK	OK	OK
OK	-0.034 NG	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK

OK	0 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.031 NG	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.05 NG	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.052 NG	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.113 NG	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK

OK	0.004 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	-0.044 NG	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.099 NG	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.207 NG	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK

OK	0.001	OK	OK	OK	OK
OK	0.011	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.021	OK	OK	OK	OK
OK	-0.396	NG	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	-0.029	OK	OK	OK	OK
OK	-0.218	NG	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.001	OK		OK	OK
OK	0	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	0	OK	OK	OK	OK

OK	0.002 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.031 NG	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.053 NG	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.041 NG	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK

OK	-0.002	OK	OK	OK	OK
OK	-0.022	OK	OK	OK	OK
OK	0.013	OK	OK	OK	OK
OK	-0.025	OK	OK	OK	OK
OK	-0.156	NG	OK	OK	OK
OK	-0.008	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.016	OK	OK	OK	OK
OK	-0.025	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	-0.025	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.041	NG	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.014	OK	OK	OK	OK
OK	-0.087	NG	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.027	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.043	NG	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK

OK	0.005 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.066 NG	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.078 NG	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK

OK	-0.004 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.043 NG	OK	OK	OK	OK
OK	-0.51 NG	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.347 NG	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.339 NG	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK

OK	0.002 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.114 NG	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.05 NG	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.096 NG	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.462 NG	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.082 NG	OK	OK	OK	OK
OK	-0.159 NG	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	-0.075 NG	OK	OK	OK	OK

OK	-0.03	OK	OK	OK	OK
OK	-0.022	OK	OK	OK	OK
OK	-0.022	OK	OK	OK	OK
OK	-0.045	NG	OK	OK	OK
OK	-0.013	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.079	NG	OK	OK	OK
OK	-0.02	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.021	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	-0.02	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.05	NG	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.029	OK	OK	OK	OK
OK	-0.029	OK	OK	OK	OK
OK	-0.014	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.009	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.05	NG	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK

OK	-0.054 NG	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.086 NG	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.071 NG	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.012 OK	OK	OK	OK	OK
OK	0.012 OK	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK

OK	0.004 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	0.024 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	0.012 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	0.024 OK	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.046 NG	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	0.014 OK	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	0.017 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.031 NG	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK

OK	0.003 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	0.012 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.025 OK	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.039 NG	OK	OK	OK	OK
OK	0.017 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	0.02 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	0.019 OK	OK	OK	OK	OK
OK	-0.058 NG	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.041 NG	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK

OK	-0.008 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	-0.085 NG	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	0.014 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	0.024 OK	OK	OK	OK	OK
OK	0.024 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.024 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.278 NG	OK	OK	OK	OK
OK	-0.035 NG	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK

OK	-0.081 NG	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.22 NG	OK	OK	OK	OK
OK	-0.22 NG	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	0.024 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.072 NG	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	-0.065 NG	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.012 OK	OK	OK	OK	OK
OK	-0.105 NG	OK	OK	OK	OK
OK	0.019 OK	OK	OK	OK	OK
OK	0.024 OK	OK	OK	OK	OK
OK	0.013 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.016 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.088 NG	OK	OK	OK	OK
OK	-0.127 NG	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK

OK	-0.007	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	0.011	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	-0.011	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.028	OK	OK	OK	OK
OK	-0.063	NG	OK	OK	OK
OK	-0.012	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.079	NG	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.017	OK	OK	OK	OK
OK	-0.03	OK	OK	OK	OK
OK	-0.014	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.009	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.016	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.024	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK

OK	0.021 OK	OK	OK	OK	OK
OK	0.02 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.067 NG	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.044 NG	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.162 NG	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.032 NG	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.075 NG	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.101 NG	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK

OK	-0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.047 NG	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.04 NG	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	-0.048 NG	OK	OK	OK	OK
OK	-0.032 NG	OK	OK	OK	OK
OK	-0.032 NG	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.072 NG	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.036 NG	OK	OK	OK	OK
OK	-0.036 NG	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK

OK	0.004 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.075 NG	OK	OK	OK	OK
OK	-0.052 NG	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK

OK	0 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.032 NG	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.133 NG	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.044 NG	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.117 NG	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK

OK	-0.004 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.222 NG	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.15 NG	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.21 NG	OK	OK	OK	OK
OK	-0.095 NG	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.055 NG	OK	OK	OK	OK
OK	-0.053 NG	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK

OK	-0.002	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK
OK	-0.014	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.009	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK
OK	-0.011	OK	OK	OK	OK
OK	-0.028	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.027	OK	OK	OK	OK
OK	-0.012	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.012	OK	OK	OK	OK
OK	-0.009	OK	OK	OK	OK
OK	-0.01	OK	OK	OK	OK
OK	-0.024	OK	OK	OK	OK
OK	-0.017	OK	OK	OK	OK
OK	-0.06	NG	OK	OK	OK
OK	-0.03	OK	OK	OK	OK
OK	-0.057	NG	OK	OK	OK
OK	-0.096	NG	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.015	OK	OK	OK	OK
OK	-0.02	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.013	OK	OK	OK	OK
OK	-0.055	NG	OK	OK	OK
OK	-0.055	NG	OK	OK	OK
OK	-0.012	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.01	OK	OK	OK	OK
OK	-0.023	OK	OK	OK	OK
OK	-0.034	NG	OK	OK	OK

OK	-0.03	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	-0.009	OK	OK	OK	OK
OK	-0.009	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	-0.011	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.011	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	-0.024	OK	OK	OK	OK
OK	-0.024	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.016	OK	OK	OK	OK
OK	-0.016	OK	OK	OK	OK
OK	-0.009	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.012	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.012	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	-0.027	OK	OK	OK	OK
OK	-0.012	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.04	NG	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.087	NG	OK	OK	OK
OK	-0.021	OK	OK	OK	OK
OK	-0.011	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.035	NG	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.019	OK	OK	OK	OK
OK	-0.01	OK	OK	OK	OK
OK	-0.017	OK	OK	OK	OK
OK	-0.012	OK	OK	OK	OK
OK	-0.012	OK	OK	OK	OK

OK	-0.023 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.058 NG	OK	OK	OK	OK
OK	-0.031 NG	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.075 NG	OK	OK	OK	OK
OK	-0.245 NG	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.049 NG	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.043 NG	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.208 NG	OK	OK	OK	OK
OK	-0.049 NG	OK	OK	OK	OK
OK	-0.049 NG	OK	OK	OK	OK
OK	-0.054 NG	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.03 NG	OK	OK	OK	OK
OK	0.015 OK	OK	OK	OK	OK
OK	0.014 OK	OK	OK	OK	OK
OK	0.035 NG	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	0.036 NG	OK	OK	OK	OK
OK	0.036 NG	OK	OK	OK	OK
OK	0.017 OK	OK	OK	OK	OK
OK	0.02 OK	OK	OK	OK	OK
OK	-0.232 NG	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	0.012 OK	OK	OK	OK	OK
OK	-0.036 NG	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.229 NG	OK	OK	OK	OK

OK	-0.089 NG	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.036 NG	OK	OK	OK	OK
OK	0.016 OK	OK	OK	OK	OK
OK	0.018 OK	OK	OK	OK	OK
OK	0.013 OK	OK	OK	OK	OK
OK	0.013 OK	OK	OK	OK	OK
OK	0.037 NG	OK	OK	OK	OK
OK	0.04 NG	OK	OK	OK	OK
OK	0.028 NG	OK	OK	OK	OK
OK	-0.081 NG	OK	OK	OK	OK
OK	0.033 NG	OK	OK	OK	OK
OK	0.035 NG	OK	OK	OK	OK
OK	0.03 NG	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.043 NG	OK	OK	OK	OK
OK	0.034 NG	OK	OK	OK	OK
OK	0.018 OK	OK	OK	OK	OK
OK	0.018 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.012 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.038 NG	OK	OK	OK	OK
OK	-0.045 NG	OK	OK	OK	OK
OK	-0.103 NG	OK	OK	OK	OK
OK	-0.049 NG	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.097 NG	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK

OK	-0.009 OK	OK	OK	OK	OK
OK	-0.12 NG	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.061 NG	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.037 NG	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	-0.063 NG	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.54 NG	OK	OK	OK	OK
OK	-0.082 NG	OK	OK	OK	OK
OK	-0.082 NG	OK	OK	OK	OK
OK	-0.034 NG	OK	OK	OK	OK
OK	-0.034 NG	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.046 NG	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.072 NG	OK	OK	OK	OK
OK	-0.072 NG	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.048 NG	OK	OK	OK	OK
OK	-0.053 NG	OK	OK	OK	OK
OK	-0.128 NG	OK	OK	OK	OK
OK	-0.07 NG	OK	OK	OK	OK
OK	-0.073 NG	OK	OK	OK	OK
OK	-0.127 NG	OK	OK	OK	OK
OK	-0.147 NG	OK	OK	OK	OK
OK	-0.147 NG	OK	OK	OK	OK
OK	-0.033 NG	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK

OK	0.004	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	-0.009	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	0.013	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	-0.03	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK

OK	-0.019 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.087 NG	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	-0.028 OK			OK	OK
OK	-0.028 OK			OK	OK
OK	-0.039 NG	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.197 NG	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK

OK	0.005 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.063 NG	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.06 NG	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.05 NG	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	0.02 OK	OK	OK	OK	OK
OK	0.02 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK

OK	0.008 OK	OK	OK	OK	OK
OK	0.017 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	0.023 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.019 OK	OK	OK	OK	OK
OK	0.016 OK	OK	OK	OK	OK
OK	0.016 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.118 NG	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.035 NG	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	0.018 OK	OK	OK	OK	OK
OK	-0.039 NG	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.023 OK	OK	OK	OK	OK
OK	0.021 OK	OK	OK	OK	OK
OK	0.024 OK	OK	OK	OK	OK
OK	0.039 NG	OK	OK	OK	OK

OK	0.025	OK	OK	OK	OK
OK	0.029	NG	OK	OK	OK
OK	0.016	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.024	OK	OK	OK	OK
OK	-0.024	OK	OK	OK	OK
OK	0.013	OK	OK	OK	OK
OK	0.004	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.011	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	-0.009	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.011	OK	OK	OK	OK
OK	-0.024	OK	OK	OK	OK
OK	0.017	OK	OK	OK	OK
OK	0.023	OK	OK	OK	OK
OK	0.014	OK	OK	OK	OK
OK	0.013	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.024	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.053	NG	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	-0.025	OK	OK	OK	OK
OK	-0.028	OK	OK	OK	OK
OK	-0.021	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.021	OK	OK	OK	OK

OK	0.001 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	0.015 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.068 NG	OK	OK	OK	OK
OK	-0.067 NG	OK	OK	OK	OK
OK	-0.094 NG	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.022 OK	OK	OK	OK	OK
OK	-0.05 NG	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.121 NG	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.048 NG	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.044 NG	OK	OK	OK	OK

OK	-0.023 OK	OK	OK	OK	OK
OK	-0.085 NG	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.077 NG	OK	OK	OK	OK
OK	-0.031 NG	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.035 NG	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.091 NG	OK	OK	OK	OK
OK	-0.032 NG	OK	OK	OK	OK
OK	-0.038 NG	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.071 NG	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK

OK	-0.048 NG	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.069 NG	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.024 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.053 NG	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.103 NG	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.117 NG	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.023 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.026 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	0.014 OK	OK	OK	OK	OK
OK	0.021 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK

OK	-0.004 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.058 NG	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.035 NG	OK	OK	OK	OK
OK	-0.075 NG	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	-0.128 NG	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.085 NG	OK	OK	OK	OK
OK	-0.088 NG	OK	OK	OK	OK
OK	-0.041 NG	OK	OK	OK	OK
OK	-0.027 OK	OK	OK	OK	OK
OK	-0.013 OK	OK	OK	OK	OK
OK	-0.187 NG	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.077 NG	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK

OK	-0.03	OK	OK	OK	OK
OK	-0.057	NG	OK	OK	OK
OK	-0.049	NG	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.088	NG	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	0.017	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.068	NG	OK	OK	OK
OK	0.015	OK	OK	OK	OK
OK	0.01	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.02	OK	OK	OK	OK
OK	0.019	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.102	NG	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	-0.028	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.074	NG	OK	OK	OK
OK	-0.074	NG	OK	OK	OK
OK	-0.015	OK	OK	OK	OK
OK	-0.015	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	0	OK	OK	OK	OK

OK	-0.002 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.057 NG	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.009 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	0.016 OK	OK	OK	OK	OK
OK	0.013 OK	OK	OK	OK	OK
OK	-0.011 OK	OK	OK	OK	OK
OK	-0.063 NG	OK	OK	OK	OK
OK	-0.121 NG	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.05 NG	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	-0.014 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.02 OK	OK	OK	OK	OK
OK	-0.047 NG	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	-0.534 NG	OK	OK	OK	OK
OK	-0.149 NG	OK	OK	OK	OK
OK	-0.028 OK	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.017 OK	OK	OK	OK	OK
OK	-0.479 NG	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.122 NG	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK

OK	-0.013 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.048 NG	OK	OK	OK	OK
OK	-0.031 NG	OK	OK	OK	OK
OK	-0.025 OK	OK	OK	OK	OK
OK	-0.089 NG	OK	OK	OK	OK
OK	-0.236 NG	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.003 OK	OK	OK	OK	OK
OK	0.017 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.012 OK	OK	OK	OK	OK
OK	0.02 OK	OK	OK	OK	OK
OK	0.016 OK	OK	OK	OK	OK
OK	0.021 OK	OK	OK	OK	OK
OK	0.01 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.025 OK	OK	OK	OK	OK
OK	0.023 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK

OK	0.003 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.011 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	-0.055 NG	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0.006 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.126 NG	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.019 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.012 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.064 NG	OK	OK	OK	OK
OK	0.009 OK	OK	OK	OK	OK
OK	-0.047 NG	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.047 NG	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.005 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK

OK	-0.017 OK	OK	OK	OK	OK
OK	-0.018 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	-0.007 OK	OK	OK	OK	OK
OK	-0.008 OK	OK	OK	OK	OK
OK	-0.021 OK	OK	OK	OK	OK
OK	-0.016 OK	OK	OK	OK	OK
OK	-0.015 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.002 OK	OK	OK	OK	OK
OK	0.004 OK	OK	OK	OK	OK
OK	0.005 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.01 OK	OK	OK	OK	OK
OK	-0.153 NG	OK	OK	OK	OK
OK	-0.044 NG	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	-0.004 OK	OK	OK	OK	OK
OK	-0.006 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	0 OK	OK	OK	OK	OK
OK	-0.094 NG	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	-0.029 OK	OK	OK	OK	OK
OK	-0.03 OK	OK	OK	OK	OK
OK	-0.061 NG	OK	OK	OK	OK
OK	-0.022 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	0.003 OK	OK	OK	OK	OK
OK	-0.001 OK	OK	OK	OK	OK
OK	0.008 OK	OK	OK	OK	OK
OK	0.002 OK	OK	OK	OK	OK
OK	0.001 OK	OK	OK	OK	OK
OK	0.007 OK	OK	OK	OK	OK

OK	-0.003	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.008	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.006	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.005	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	0.007	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	0.009	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.013	OK	OK	OK	OK
OK	-0.015	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	-0.033	NG	OK	OK	OK
OK	-0.117	NG	OK	OK	OK
OK	-0.018	OK	OK	OK	OK
OK	-0.071	NG	OK	OK	OK
OK	-0.022	OK	OK	OK	OK
OK	-0.022	OK	OK	OK	OK
OK	-0.069	NG	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	0.002	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK

OK	-0.007	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.011	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK
OK	0.001	OK	NG	OK	OK
OK	0.001	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.009	OK	OK	OK	OK
OK	-0.007	OK	OK	OK	OK
OK	0.003	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	0.001	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.001	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.002	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.008	OK	OK	OK	OK
OK	-0.005	OK	OK	OK	OK
OK	-0.004	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.006	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.016	OK	OK	OK	OK
OK	-0.003	OK	OK	OK	OK
OK	-0.019	OK	OK	OK	OK
OK	-0.015	OK	OK	OK	OK